

ASS. REC. BY:

REF:

C12 / 220013421ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.81%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SW 80325 Yr Regn: 03.18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Hyundai Elantra 1591

Colour:

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

21905

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM140841CMJU 031911

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/1/12

D.O.I.

10/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ

15/2 81645.28 Cahr

Date/Time, File Page to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SLW8032S

No.	Qty	List Items	
1	1	Front RH side mirror assy	<i>ny</i> \$ <i>Di</i> 638.60 ✓
2	1	Rear RH door	\$ <i>n</i> 1,878.30 X
3	1	Rear RH door outer handle	\$ <i>na</i> 68.00 ✓
4	1	Rear RH fender	\$ <i>n</i> 1,892.00 X
5	1	Rear RH fender 1/4 glass moulding	\$ <i>na</i> 70.50 X
			\$ 4,547.40
		Less 20%	\$ 909.48
		Total :	\$ 3,637.92

Special Nett Items

6	1 set	Rear windscreen & rear RH fender glass sealant	\$ <i>na</i> 80.00 X
---	-------	--	----------------------

Labour

1	Labour Charges for remove/refit, cut/weld, panel beat and replacement of damages.	\$ 1,200.00	<i>500l</i>
2	To putty and spray Spray Paintings charges.	\$ 1,000.00	<i>500l</i>
3	To check wirings.	\$ 40.00	<i>20l</i>
4	To remove. Refit rear windscreen glass.	\$ <i>na</i> 140.00	X
5	To remove, refit rear RH fender 1/4 glass.	\$ <i>na</i> 100.00	X
6	To remove, refit roof lining, rear cushion and attachments.	\$ 200.00	<i>60l</i>
7	To supply and apply anti rust treatment	\$ <i>na</i> 80.00	X
	Total :	\$ 2,760.00	

Total Parts and Labour : \$ 6,477.92

Not Authorized

Resurvey B4 pain

@ 1645.28

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: