



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD  
10 MARINA BOULEVARD  
#48-01 MARINA BAY FINANCIAL CENTRE TOWER  
2SINGAPORE 018983  
ATTN:VALE OH

Ref: CC4/ASM22001344/Apa3q2

Date: 20/03/2023

Code: HSB

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHD 3646B	<b>Veh. Inspected</b>	SMU 8384A
<b>Policy No.</b>	P2465679	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03SW5	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	11/02/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ E250	<b>c.c</b>	1796
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	WDD2120472A102283	<b>Colour</b>	PURPLE
<b>Odometer</b>	155793 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	245/40 R18	CONTINENTAL	6 mm
<b>L/H Front Tyre</b>	245/40 R18	CONTINENTAL	6 mm
<b>R/H Rear Tyre</b>	245/40 R18	CONTINENTAL	6 mm
<b>L/H Rear Tyre</b>	245/40 R18	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	07/02/2022	<b>Inspection Date</b>	11/02/2022
<b>Survey held at</b>	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**