



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001359/Uqf3n2	
			Date: 28/02/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJJ 6192T	Veh. Inspected	SGR 1207L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200518/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	14/02/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI COLT RALLIART VERSION-R (M)	c.c	1468	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	Z27A0400195	Colour	RED	
Odometer	130155 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/45 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/45 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/45 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/02/2022	Inspection Date	14/02/2022	
Survey held at	BLK 15 KAKI BUKIT RD 4, BARTLEY BIZ #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>7 Working Days</b>	