

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gabriel Wee

Date: 07 Apr 2022

Preliminary Advice

Vehicle No	: SNC470U	Accident Date	: 22/01/2022
Make	: MAZDA 3	Policy No.	: D18MFL0003414_02
Assignment Date	: 14/02/2022	Excess	: S\$1,500.00
Date of Inspection	: 14/02/2022	Est. Duration of Repair	: 14
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,931.31	(incl.supplementary \$5582.48)
Revised Amount	:S\$	29,737.39	
Check Items (Estimated)	:S\$	4,013.04	
Total	:S\$	33,750.43	(incl.supplementary \$5582.48)
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	47,449.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,551.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approved on the supplementary