

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Feb 2022)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SNC470U/11/02/2022 13:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*BONNET	B ₁	20.00	0.00	*1,040.80 FL	✓
2	1		*BONNET LOCK	D ₁	20.00	0.00	*164.40 FL	7✓
3	1		*BONNET HINGE LH	B ₁	20.00	0.00	*48.80 FL	✓
4	1		*BONNET HINGE RH	D ₁	20.00	0.00	*48.80 FL	✓
5	1		*BONNET INSULATOR	CM	20.00	0.00	*159.00 FL	✓
6	10		*BONNET INSULATOR CLIPS	N ₁	20.00	0.00	*27.00 FL	✓
7	1		*FRT BUMPER	T ₁	20.00	0.00	*867.30 FL	✓
8	1		*FRT BUMPER SIDE RETAINER LH	D ₁	20.00	0.00	*20.50 FL	✓
9	1		*FRT BUMPER SIDE RETAINER RH	S ₁	20.00	0.00	*20.50 FL	X
10	1		*FRT BUMPER FOG LAMP GARNISH LH	S ₁	20.00	0.00	*20.50 FL	X
11	1		*FRT BUMPER REINFORCEMENT	R	20.00	0.00	*541.70 FL	X
12	10		*FRT BUMPER CLIPS	N ₁	20.00	0.00	*30.00 FL	✓
13	1		*FRT GRILLE	S ₁	20.00	0.00	*163.10 FL	7X
14	1		*FRT GRILLE TOP PANEL	B ₁ CM	20.00	0.00	*453.00 FL	✓
15	1		*FRT GRILLE TOP GARNISH	CM	20.00	0.00	*551.70 FL	✓
16	1		*FRT GRILLE CHROME MOULDING LH	CM	20.00	0.00	*298.00 FL	✓
17	1		*FRT GRILLE CHROME MOULDING RH	S ₁	20.00	0.00	*298.00 FL	X
18	1		*HEADLAMP LH	B ₁	20.00	0.00	*2,076.00 FL	✓
19	1		*HEADLAMP LOWER BRACKET LH	CM	20.00	0.00	*56.20 FL	✓
20	1		*LH FRT FENDER	B ₁	20.00	0.00	*415.90 FL	✓
21	1		*LH FRT FENDER INNER PANEL SIDE	B ₁	20.00	0.00	*359.30 FL	✓
22	1		*LH FRT FENDER INNER PANEL TOP	B ₁	20.00	0.00	*367.69 FL	✓
23	1		*LH FRT FENDER INNER SHIELD	CM	20.00	0.00	*73.20 FL	✓
24	10		*LH FRT FENDER INNER SHIELD CLIPS	N ₁	20.00	0.00	*30.00 FL	✓
25	1		*LH FRT FENDER TOP GARNISH	B ₁	20.00	0.00	*345.20 FL	✓
26	1		*LH FRT DOOR	B ₁	20.00	0.00	*1,127.50 FL	✓
27	1		*LH FRT DOOR TOP HINGE	D ₁	20.00	0.00	*51.70 FL	✓
28	1		*LH FRT DOOR BOTTOM HINGE	B ₁	20.00	0.00	*41.70 FL	✓
29	1		*LH FRT DOOR CHECKER	B ₁	20.00	0.00	*44.20 FL	✓
30	1		*LH FRT DOOR BLACK STICKER	N ₁	20.00	0.00	*75.20 FL	✓
31	1		*LH FRT DOOR OUTER MOULDING	W ₁	20.00	0.00	*80.00 FL	✓
32	1		*LH FRT DOOR LOCK	R	20.00	0.00	*223.40 FL	X
33	1		*LH FRT DOOR INNER TRIM	S ₁	20.00	0.00	*989.30 FL	7X
34	1		*LH WING MIRROR	B ₁	20.00	0.00	*563.80 FL	✓
35	1		*LH WING MIRROR COVER	N ₁	20.00	0.00	*75.30 FL	✓
36	1		*LH REAR DOOR	R	20.00	0.00	*954.10 FL	X
37	2		*LH REAR DOOR BLACK STICKER	N ₁	20.00	0.00	*126.00 FL	X
38	1		*RH FRT RIM 16	N ₁	20.00	0.00	*454.80 FL	✓
39	1		*FRT WINDSCREEN GLASS	CM	20.00	0.00	*1,280.00 FL	✓
40	1		*FRT WINDSCREEN GLASS MOULDING	N ₁	20.00	0.00	*86.00 FL	✓
41	1		*SEALANT	N ₁	0	0.00	*40.00 FS	✓
42	1		*INNER SEAL	N ₁	0	0.00	*30.00 FS	✓
43	1		*ERP BRACKET	N ₁	0	0.00	*26.00 FS	✓
44	1		*SOLAR FILM	N ₁	0	0.00	*300.00 FS	7X
45	1		*FRT SUPPORT PANEL	B ₁	20.00	0.00	*1,021.00 FL	7✓

ComfortDelGro Engineering Pte Ltd/SNC470U/11/02/2022 13:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
46	1		*FRT SUPPORT PANEL TOP GARNISH	Nil	20.00	0.00	138.80 FL	✓
47	1		*AIRCON CONDENSOR	By Pex	20.00	0.00	945.90 FL	X ✓
48	1		*RADIATOR	Sn	20.00	0.00	1,053.00 FL	X
49	1		*RADIATOR FAN COWLING	Sn	20.00	0.00	536.70 FL	X
50	1		*AIR DUCT TOP	Sn	20.00	0.00	94.20 FL	7X
51	1		*AIR DUCT BOTTOM	Sn	20.00	0.00	98.30 FL	X
52	1		*AIR CLEANER BOX TOP	Sn	20.00	0.00	65.10 FL	7X
53	1		*AIR CLEANER BOX BOTTOM	Sn	20.00	0.00	59.90 FL	7X
54	1		*LH FRT WHEEL HOUSE	By	20.00	0.00	756.30 FL	✓
55	1		*FUSE BOX TOP	CM	20.00	0.00	54.40 FL	✓
56	1		*FUSE BOX BOTTOM	CM	20.00	0.00	1,123.00 FL	✓
57	1		*LH ROCKER PANEL GARNISH	CM	20.00	0.00	757.70 FL	✓
58	1		*DRIVER STEERING AIRBAG	Avr	20.00	0.00	1,526.80 FL	✓
59	1		*DRIVER STEERING AIRBAG CLOCK SPRING	Avr	20.00	0.00	587.70 FL	✓
60	1		*DRIVER LEG AIRBAG	Avr	20.00	0.00	1,226.38 FL	✓
61	1		*DRIVER SEAT BELT	Tm	20.00	0.00	1,102.81 FL	✓
62	1		*DRIVER SEAT BELT BUCKLE	Sn	20.00	0.00	118.20 FL	7X
63	1		*FRT PASSANGER AIRBAG	Avr	20.00	0.00	1,388.40 FL	✓
64	1		*FRT PASSANGER SEAT BELT	Tm	20.00	0.00	1,102.81 FL	✓
65	1		*FRT PASSANGER SEAT BELT BUCKLE	Sn	20.00	0.00	131.80 FL	7X
66	1		*AIRBAG CONTROL UNIT	Avr	20.00	0.00	1,309.50 FL	✓
67	1		*DASHBOARD	Tm	20.00	0.00	2,161.30 FL	✓
68	1		*LH FRT SHOCK ABSORBER	By	20.00	0.00	346.90 FL	7 ✓
69	1		*LH FRT KNUCKLE ARM	By	20.00	0.00	375.60 FL	7 ✓
70	1		*LH FRT KNUCKLE BEARING	Avr	20.00	0.00	507.70 FL	7 ✓
71	1		*LH FRT LOWER ARM	Sn	20.00	0.00	454.10 FL	7X
72	1		*WIPER GARNISH LH	Sn	20.00	0.00	162.40 FL	X
73	1		*WIPER GARNISH SIDE LH	Nil	20.00	0.00	12.90 FL	✓
74	1		*BATTERY BASE	cracked	20.00	0.00	345.60 FL	X ✓
75	1		*PRIVATE HIRE DECAL	Avr	0	0.00	50.00 FS	25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,660.79
- List Item Discount on L Items (\$\$)	6,842.96
Total Parts (\$\$)	27,817.83

ComfortDelGro Engineering Pte Ltd/SNC470U/11/02/2022 13:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

15769.5

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE AND INSTALL FRT WINDSCREEN GLASS	New	120.00 ✓
2	TO CONDUCT WHEEL ALIGNMENT	New	100.00 <i>da</i>
3	TO CUT, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS BONNET, FRT GRILLE, FRT BUMPER, LH FRT FENDER, LH FRT WHEEL HOUSING, LH FRT DOOR, LH REAR DOOR, LH ROCKER PANEL GARNISH, FRT SUPPORT PANEL AND ETC	New	<i>1680</i> 1,920.00
4	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, LH FRT FENDER, LH FRT WHEEL HOUSING, LH FRT DOOR, LH REAR DOOR, LH ROCKER PANEL GARNISH, FRT SUPPORT PANEL AND ETC	New	<i>1750</i> 2,200.00
	TO REMOVE AND INSTALL AIRBAG SYSTEM	New	<i>200</i> 250.00 ✓
6	TO RESET AND REPROGRAM AIRBAG SYSTEM	New	<i>450</i> 200 250.00 <i>250</i>
7	TO REMOVE AND INSTALL DASHBOARD	New	250.00 ✓
8	TO REMOVE AND INSTALL LH FRT UNDER CARRIAGE	New	<i>an</i> 120.00 <i>7X</i>
9	TO DISCHARGE AND CHARGE AIRCON GAS	New	100.00 ✓
10	TO TRANSFER BOTH SUDE DOORS INNER PART FROM DAMAGE TO NEW DOORS	New	160.00 <i>da</i>
11	TO CHECK WIRING AND LIGHTING	New	50.00 <i>20</i>
Gross Labour Cost (S\$)			5,520.00

ComfortDelGro Engineering Pte Ltd/SNC470U/11/02/2022 13:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

To = Kenneth

Parts = 28103.89

+ Supp = 6978.10

= 35081.99

- 20% *7016.39*

= 28065.60

+ SN *386.00*

+ Labon *4730.00*

= 33181.60 ~~*33193.07*~~

26/1/22 *Quidy*

4730

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Apr 2022)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SNC470U/07/04/2022 08:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH FRT DOOR WEATHER STRIP torn	20.00	0.00	*96.60 FL
2	1		*LH WING MIRROR SIGNAL LAMP cracked	20.00	0.00	*124.30 FL
3	1		*PETROL UNIT CONVERTER RELAY BRACKET cracked	20.00	0.00	*140.10 FL
4	1		*HEADLAMP SIGNAL BULB SOCKET LH broken	20.00	0.00	*28.20 FL
5	1		*BONNET LOCK TOP COVER cracked	20.00	0.00	*19.10 FL
6	1		*LH FRT SHOCK ABSORBER TOP MOUNTING bent	20.00	0.00	*95.00 FL
7	1		*RH FRT FENDER STAY FRT bent	20.00	0.00	*66.40 FL
8	1		*FRT FENDER TOP RETAINER LH cracked	20.00	0.00	*46.10 FL
9	1		*WIRE HARNESS torn	20.00	0.00	*5,942.00 FL
10	1		*HEADLAMP HID UNIT LH dented	20.00	0.00	*420.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,978.10
- List Item Discount on L Items (\$\$)	1,395.62
Total Parts (\$\$)	5,582.48

ComfortDelGro Engineering Pte Ltd/SNC470U/07/04/2022 08:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2022)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SNC470U/28/04/2022 10:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*LH FRT TYRE 90% cut	0	0.00	*240.00 FS	216
Total Parts (\$\$)						240.00	

F=Franchise part. S=SpcNett.

ComfortDelGro Engineering Pte Ltd/SNC470U/28/04/2022 10:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS