

# AutoSoon Pte Ltd

176 Sin Ming Drive #01-10  
Sin Ming Autocare Singapore 575721  
Tel No. 6452 6657 Fax No. 6451 4618  
Email: autosoon1@gmail.com  
UEN: 200709808N  
GST Reg No: 200709808N

Tax Invoice No: AS 862876

PO Number:

Date: May 13, 2022

Car Plate No: SNC 470 U

3\_1.5A

Chassis:

Remark: SRS/Parking sensors malfunction

Attn: Patrick Tia 96567133

Mileage: 5912 KM

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road West Wing Level 4 Singapore 579701  
PHONE: 8718 8578 Brandon FAX: 6284 4284

S.No	Quantity	Particular	Unit Price	Amount (SGD)
1	1	SRS malfunction To computer check/diagnosis SRS malfunction and reprogram/recoding SRS module in repair.	450.00	450.00
2	1	Miscellaneous To computer check the parking sensors module and rectify the wiring harness, refix plugs behind instrument panel in repair	200.00	200.00

Sub Total	650.00
GST 7%	45.50
Total	695.50
Paid Amount	0.00
Total Due	695.50

Terms Of Payment: Due upon receipt



Customer's Signature/Co. Stamp



For AutoSoon Pte Ltd

Bank A/C: Ocbc 568-865-323-001

PayNow ID: 200709808N



I/We agree to pay all work and parts required for the repairs described above at your retail charge. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions.