



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GT7575Z NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear door LH / <i>OD</i>		1336.00	
1	Rear door Lh center outer garnish <i>X</i> / <i>cut</i>		352.00	
1	Rear door RH / <i>OD</i>		1002.00	
1	Rear wiper arm / <i>cut</i>		65.00	
1	Rear wiper arm cover garnish / <i>mis</i>		15.00	
1	Rear bumper / <i>CR4</i>		486.00	
2	Rear bumper side retainer LH/RH @2*\$38 / <i>BR</i>		76.00	
1	End panel <i>X R</i>		178.00	
<i>2</i> 1	Tail lamp LH/RH @2*\$278 (<i>LH</i>) / <i>BR</i>		556.00	<i>278 -</i>
1	Rear bumper towing cover <i>X nn</i>		28.00	
1	Rear trunk weatherstrip / <i>TN</i>		112.00	
Part Items Total:			4206.00	
			-10% -420.60	
			3785.40	
SPECIAL NETT ITEMS				
1	Rear carplate / <i>CM</i>		35.00	
1	Rear reverse sensor / <i>shkl</i>		200.00	
1	End panel sealant <i>X nn</i>		60.00	
1	Rear windscreen sealant LH / <i>MC</i>		<i>30</i> 50.00	
1	Rear windscreen sealant RH / <i>MC</i>		<i>30</i> 50.00	
1	70km/H sticker / <i>MC</i>		20.00	
1	6 pax sticker / <i>MC</i>		20.00	
2	Rear door LH/RH Company sticker and decal / <i>MC</i>		<i>600</i> 900.00	
SN Items Total:			1335.00	
Total Parts			5120.40	

3722
-10%
3349.80

935



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GT7575Z NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove and refit/replace rear compartment fitting, trimmings, garnish and etc	100.00	30
6	To remove and refit/replace rear door LH fitting, trimmings, garnish, window glass and mechanism	150.00	50
7	To remove and refit/replace rear door RH fitting, trimmings, garnish, window glass and mechanism	150.00	120
8	To remove and replace rear reverse sensor	100.00	30
Labour Total :		2420.00	
TOTAL (PARTS & LABOUR):		7540.40	

1190

Steve (LKK)

17/2/22, 12p

W H R

L/S

17 AL H
S H

= 5474.80

LS- 4379.84

= 4400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: