

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001364/UPA3Q2**Date:** 12/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800012178
Claimant Vehicle No :	GBF187P	Insured Vehicle No :	SLW4373J
Date of Loss:	07/02/2022	Nature of Claim:	TP
		Claim No:	2335431718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF187P	Engine No:	1KD2617301
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y80K206478
Reg. Date:	31/05/2016 (Man. Year: 2016)	Odometer:	163937 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	CST TIRE 6 mm	Rear Left Side:	Maxxis 6/6 mm
Front Right Side:	CST TIRE 6 mm	Rear Right Side:	Maxxis 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,085.50	3,226.40	3,859.10	54.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,310.00	370.00	22.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,765.50	4,536.40	4,229.10	48.25
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	8,765.50	3,600.00	5,165.50	58.93
+ GST 7.00/7.00% (S\$)	613.59	252.00	361.59	58.93
Nett Amount (S\$)	9,379.09	3,852.00	5,527.09	58.93
+ Car Rental (4.0 x S\$90.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,239.20		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment:	14/02/2022	
Date Inspected:	14/02/2022	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT DOOR	Badly Dented	1,294.80 F	*1,294.80 FL
2	1		*RIGHT DOOR COMPANY STICKER	Necessary	120.00 FS	*80.00 FS
3	1		*RIGHT DOOR SIDE MARKING (LTA)	Necessary	25.00 FS	*25.00 FS
4	1		*RIGHT DOOR HINGE	Lower Bent	342.80 F	*145.50 FL
5	1		*RIGHT DOOR INNER TRIM BOARD	Torn	781.10 F	*581.10 FL
6	1		*RIGHT DOOR ARC RUBBER	Torn	132.80 F	*132.80 FL
7	1		*RIGHT DOOR PILLAR	Repair	641.40 F	*- FL
8	1		*RIGHT CABIN ARC PANEL	Repair	374.50 F	*- FL
9	1		*RIGHT CABIN ARC PANEL RUBBER	Torn	89.10 F	*89.10 FL
10	1		*RIGHT STEP GARNISH	Cracked	377.10 F	*345.50 FL
11	1		*FRONT RIGHT RIM	Bent	200.00 FS	*50.00 FS
12	1		*FRONT RIGHT TYRE	Serviceable	200.00 F	*- FL
13	1		*RIGHT CORNER PANEL	Repair	355.60 F	*- FL
14	1		*RIGHT HEADLAMP	Scratched	987.20 F	*861.10 FL
15	1		*FRONT BUMPER	Distorted	854.30 F	*645.30 FL
16	1		*FRONT BUMPER REINFORCEMENT	No such part	279.80 F	*- FL
17	1		*FRONT LICENCE PLATE	Not Necessary	30.00 F	*- FL
					Sub Total (S\$)	7,085.50 4,250.20
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 1,023.80
					Total Parts (S\$)	7,085.50 3,226.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR	New	120.00	60.00
2	CHECK WIRING	New	80.00	20.00
3	ANTI RUST PROOF	New	80.00	50.00
4	PANEL BEATING	New	600.00	500.00
5	PAINT WORK	New	800.00	680.00
Gross Labour Cost (\$)			1,680.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >