

Vehicle: GBF187P

Make & Model: TOYOTA DYNA

Chassis No: JTFAT35Y80K206478

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Right Door			\$ 1,294.80	body.20 ✓
2	Right Door Company Sticker			\$ 120.00 SN	rec 80 s/n
3	Right Door Side Marking (LTA)			\$ 25.00 SN	rec 25 s/n
4	Right Door Hinge	2	145.50 \$171.40	\$ 342.80	lower dent 12 c
5	Right Door Inner Trim Board		581.10	\$ 781.10	Torn ✓
6	Right Door ARC Rubber			\$ 132.80	Torn ✓
7	Right Door Pillar			\$ 641.40	R x
8	Right Cabin ARC Panel			\$ 374.50	R x
9	Right Cabin ARC Panel Rubber			\$ 89.10	Torn ✓
10	Right Step Garnish		345.50	\$ 377.10	cm ✓
11	Front Right Rim			\$ 200.00 SN	345 50 s/n
12	Front Right Tyre			\$ 200.00 SN	su x
13	Right Corner Panel			\$ 355.60	R x
14	Right Headlamp		861.10	\$ 987.20	scr ✓
15	Front Bumper		645.30	\$ 854.30	Dis ✓
16	Front Bumper Reinforcement		252	\$ 279.80	ns x
17	Front Licence Plate			\$30.00	17 x
18					
Labour					
1	Transfer Door			\$ 120.00	60
2	Check Wiring			\$ 80.00	20
3	Anti Rust Proof			\$ 80.00	50
4	Panel Beating			\$ 600.00	500

5	Paint Work			\$ 800.00	680
---	------------	--	--	-----------	-----

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Not Allowed
 14/2/22
 2 / \$ 3600 /
 4 days
 telephone 111

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-4095.20
 252
 P-3071.40
 S.N- 15500
 L- 1310.00
 4536.40
 20%
 3628