

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0095/2022/JT
DATE : 9-Feb-22
WIP : 11057

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PRASANNA SUDHINDRA RAO
ADDRESS : BLK1 SENGKANG EAST AVE
#11-01
SINGAPORE 544811
TELEPHONE : HP +65 96542110
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700032642-04
VEHICLE NO : **SLQ 8792 M**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 25/7/2017
ENGINE NO : CVN 040594
CHASSIS NO : WAUZZZF40HA177260
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Feb-22
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183

55 UBI ROAD 1, SINGAPORE 408699

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

TEL : 6366 2323 FAX : 6841 1183

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLQ 8792 M

SURVEYOR'S RECOMMENDATION	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WAHSER ASSY.	S/N \$ 360.00	X
	2	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280 ✓
	3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS A-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,150.00	1500 ✓
	4	TO RESPRAY LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS A-PILLAR AND LHS WING MIRROR COVER.	\$ 4,000.00	1100 ✓
	5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES			: \$ 8,052.00	



55, UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55, UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 8792 M

ESTIMATED LABOUR CHARGES FOR

S/N	PARTS DESCRIPTION	QTY	ESTIMATED CHARGES	FIXED S/NETT	DAMAGED PARTS & PRICES	REMARKS
1	FRONT FENDER - LH <i>Dented</i>	1	\$	861.00	✓	688.8
2	FRONT FENDER ATTACHMENT PARTS- <i>new</i>	1	\$	211.00	x	
3	FRONT FENDER CLOSING ELEMENTS - LH	1	\$	37.00	x	
4	FRONT FENDER BRACKET - LH ?	1	\$	36.00	x	
5	FRONT FENDER LEDGE LONG COVER - LH ?	1	\$	35.00	x	
6	FRONT FENDER LEDGE SHORT COVER - LH ?	1	\$	26.00	x	
7	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$	260.00	x	
8	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$	219.00	x	
9	FRONT STONE CHIP GUARD <i>new</i>	1	\$	57.00	x	
10	FRONT DOOR - LH <i>Dented</i>	1	\$	3,431.00	✓	2744.8
11	FRONT DOOR BUNGS - LH <i>new</i>	2	\$	10.00	x	
12	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$	229.00	✓	182.8
13	BONDING AGENT ?	1	\$	51.00	x	
14	CLEANING SOLUTION ?	1	\$	74.00	x	
15	APPLICATOR ?	1	\$	8.00	x	
16	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$	1,153.00	x	960.8
17	FRONT DOOR CATCH - LH ?	1	\$	105.00	x	
18	WING MIRROR MOUNTING - LH <i>new</i>	1	\$	1,201.00	✓	
19	WING MIRROR CAP - LH <i>new</i>	1	\$	308.00	x	73.60
20	SUNDRIES ?		\$	350.00	x	
TOTAL SPARE PARTS		:	\$	8,662.00		
TOTAL LABOUR CHARGES		:	\$	8,052.00		
GRAND TOTAL		:	\$	16,714.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

VEHICLE REGISTRATION NO. SLO 8792 M

ESTIMATED LABOUR/MATERIAL LIST FOR ACCIDENT VEHICLE

NAME : Adnan L
 SURVEYED DATE : 11/02/22
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : Not Authorised, 05 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT