CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY SINGAPORE 417883 Not Authorit
14/2/22
1/5 \$ 4500/
5days

	VEHICLE No: GBB 528K		NETT ITEM
1PC 2PCS 2PCS 2PCS 1PC 1PC 1PC 1PC 1PC 1PC	REAR TAILGATE REAR TAILGATE LOCK LATCHS @\$ REAR TAILGATE LOCK LOWER 'L' B REAR TAILGATE LOCK LOWER "L" TAILLAMPS @\$450.00 TAILLAMP HOUSING PANELS @\$1 REAR LICENCE PLATE BRACKET REAR LICENCE PLATE LAMP REAR EXHAUST REAR EXHAUST REAR EXHAUST MOUNTING REAR END PANEL REAR SPARE TYRE CARRIER & CHA DROPSIDE GATE PANEL N/S DROPSIDE GATE PANEL O/S	BRACKETS @\$180.00 BRACKER RUBBERS @\$120.00 CAL 290 X 2 = 5 80.00 MA Sent SNO MA SO/Sent MA SO/Sent	
	S.NETT		
1SET 1SET 1PC 1PC	REAR TAILGATE '70km/h & 13pax REAR REVERSE SENSOR REAR LICENCE PLATE REAR STEP WOODEN	STICKER Mer Shaped Surf cre	\$50.00 200 \$300.00 200 \$50.00 14 \$400.00 200
	TO CHECK WIRING TO DISMANTLE & REPLACED REVE TO DISMANTLE & REPLACED REAR TO STRAIGHTEN & REALIGN CHASE TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & R TO PUTTY & SPRAY PAINTING	SIS Refer 106 on	\$50.00 20 \$100.00 \$0 \$800.00 3 \$0 \$1,000.00 \$ \$2,200.00 60 \$2,200.00 7000 \$1,800.00 \$0 \$1,800.00 \$0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3245.80 2-2921-22 5.N-434 5.07-2280 4508