

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0060/2022/JT
DATE : 24-Jan-22
WIP : 64756

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 28/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 14 Apr 22

OWNER'S NAME : MR NG SAI KIN (WU SHIJIAN)
ADDRESS : 7 BISHAN STREET 15
#24-08
SINGAPORE 573908
TELEPHONE : HP +65 9661 5580
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800129481-03
VEHICLE NO : **SMF 1243 Z**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 29/10/2018
ENGINE NO : CZE 802055
CHASSIS NO : WAUZZZ8V1J1082735
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Jan-22
PLACE OF ACCIDENT : JUNCTION OF CTE TURNING RIGHT
INTO ANG MO KIO AVE 3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 1243 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	\$	750.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$	2,000.00	\$	1,100.00
4	TO RENEW LHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK.	S/N \$	280.00	\$	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 4,152.00	\$	2,602.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1243 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	
2	REAR BUMPER FIXING PARTS	1	\$ 201.00	
3	REAR BUMPER ADAPTER - LH	1	\$ 42.00	
4	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	
5	REAR BUMPER SPOILER - LH	1	\$ 264.00	
6	REAR LIGHT REFLECTOR - LH	1	\$ 46.00	
7	REAR BUMPER GUIDE SECTION LOWER - LH	1	\$ 75.00	
8	REAR WHEEL HOUSING LINER - RH	1	\$ 260.00	
9	ALUMINIUM RIM	1	\$ 1,303.00	\$ 1,042.40
10	SUNDRIES		\$ 250.00	\$ 2.96
TOTAL SPARE PARTS		:	\$ 4,421.00	\$ 1,045.36
TOTAL LABOUR CHARGES		:	\$ 4,152.00	\$ 2,602.00
GRAND TOTAL		:	\$ 8,573.00	\$ 3,647.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-30/03/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT