

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised
Penalty B4paler
5 days
8611984

CHIAN TAIHING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-11
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: ACCIDENT CLAIMS DEPARTMENT

ESTIMATE

DATE : 07.02.2022
VEHICLE NO : SLQ600L
VEH MAKE/MODEL : HONDA VEZEL
YOM : 2017
CHASSIS NO : RU31244333
DATE OF ACCIDENT : 07.02.2022

NO	QTY	DESCRIPTION	AMOUNT \$
LIST PRICE:-			
1	1	FRONT BONNET	\$ 854.10
2	1	FRONT BONNET HINGE <i>ole x2</i>	\$ 50.00
3	1	FRONT BONNET LOCK	\$ 124.20
4	1	FRONT BONNET SEAL	\$ 36.80
5	1	FRONT BONNET STOPPER	\$ 10.90
6	1	FRONT HEADLAMP LH <i>1850</i>	\$ 1,999.30
7	1	FRONT HEADLAMP RH <i>1850</i>	\$ 1,999.30
8	2	FRONT HEADLAMP LOWER BRACKET LH & RH	\$ 68.40
9	2	FRONT HEADLAMP CHROME	\$ 280.00
10	1	FRONT GRILLE TOP OUTER GARNISH <i>421-60</i>	\$ 434.50
11	1	FRONT GRILLE TOP RUBBER	\$ 194.20
12	1	FRONT GRILLE BASE	\$ 301.80
13	1	FRONT GRILLE CHROME LOWER	\$ 71.20
14	1	FRONT EMBLEM "H"	\$ 30.00
15	1	FRONT BUMPER <i>801-70</i>	\$ 898.30
16	2	FRONT BUMPER SIDE RETAINER	\$ 47.80
17	1	FRONT BUMPER TOW COVER	\$ 18.30
18	2	FRONT BUMPER SIDE GARNISH LH & RH	\$ 70.00
19	1	FRONT FOGLAMP LH	\$ 280.00
20	1	FRONT FOGLAMP RH	\$ 280.00
21	1	FRONT LOWER GRILLE	\$ 84.20
22	1	FRONT LH FENDER	\$ 421.10
23	1	FRONT LH FENDER SHIELD	\$ 125.90
24	1	FRONT RH FENDER	\$ 421.00
25	1	FRONT RH FENDER SHIELD	\$ 125.90
26	1	FRONT SUPPORT PANEL	\$ 526.50
27	1	FRONT REINFORCEMENT BAR	\$ 293.40
28	1	FRONT RADIATOR TOP COVER / GARNISH	\$ 61.30
29		<i>Brake Panel</i> <i>CRA ✓</i> <i>76-20</i>	
30			
31			
TOTAL - LIST ITEM			\$ 10,108.40
LIST 20%			\$ 2,021.68
TOTAL			\$ 12,130.08

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

CHIAN TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-11
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 07.02.2022
VEHICLE NO : SLQ600L
VEH MAKE/MODEL : HONDA VEZEL
YOM : 2017
CHASSIS NO : RU31244333
DATE OF ACCIDENT : 07.02.2022

NO	QTY	DESCRIPTION	AMOUNT \$
SPECIAL NETT ITEMS:-			
1	1	CAR PLATE NUMBER WITH HOLDER	\$ 50.00
2	SET	FRONT BUMPER CLIPS	\$ 45.00
3	SET	FRONT BONNET INSULATOR CLIPS	\$ 45.00
4	SET	FRONT RADIOTR CLIPS COVER / GARNISH CLIPS	\$ 45.00
5	2 SET	FRONT FENDER INNER SHIELD CLIPS LH & RH	\$ 80.00
6			
Total - SN Item			\$ 265.00
Labour Charges:-			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 1,000.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 1,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$ 100.00
4		TO APPLY ANTI RUST TREATMENT	\$ 120.00
		TO REMOVE/REFIX NECESSARY ATTACHMENT SUPPORT PANEL	\$ 280.00
Total - L/C			\$ 2,500.00
Sub-Total			\$ 14,895.08
7% GST			\$ 1,042.66
Total			\$ 15,937.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: