



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22001387/Uqy3e2	
			Date: 20/05/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 7569E	Veh. Inspected	PC 9145B	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D14702202	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	14/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GDH2232002326	Colour	SILVER	
Odometer	54262 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	5 mm	
L/H Front Tyre	195 R15	MICHELIN	5 mm	
R/H Rear Tyre	195 R15	MICHELIN	5 mm	
L/H Rear Tyre	195 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2022	Inspection Date	17/03/2022	
Survey held at	AUTOBAY @ KAKI BUKIT #01-04			
Repairer	KT GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	