

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 9145B

at Workshop m/s K7 GARAGE

of 10.30

Insured: GBE756K

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$80k.

IDAC Accident Rpt: \_\_\_\_\_

Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LTA 18685

Date / Time Action / Instruction Rep 9.500

Veh No: PC 9145B

Yr Regn: 13/2/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / commuter

Make: Toyota hiace

c.c 2754

Colour: silver

A/C: Insured / Std / NI / NA

Sp. Reading: 54262

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GDH 2232002326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R 15-

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 6/1/22

D.O.I. 17/3/22

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$

) S + RS, \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL



**KT  
GARAGE**

**KT GARAGE PTE LTD** UEN: 201906115R  
Auto Bay@ Kaki Bukit Entrance A  
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date :

TO: United Overseas Insurance Ltd.  
146 Robinson Road, #02-01  
UOI Building, 068909

Total Pages :

Our Customer : KT Leasing  
Vehicle No : PC9145B  
Model : Toyota Hiace Commuter

Manufacture Year : 2019  
Date of Accident : 6/1/2022

Total Estimate Repair Days : 5

Attn : Motor Claim Department

Email : [Claims@uoi.com.sg](mailto:Claims@uoi.com.sg)

Re: Repair Estimate For Third Party Claim against : GBE7569E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Rear Bumper	1.00	\$486.10	\$486.10	700/0e ✓
2	Rear Bumper Clip	6.00	\$1.50	\$9.00	1m ✓
3	Rear Bumper Lower Bracket	1.00	\$200.00	\$200.00	su X
4	Rear End Panel Outer	1.00	\$155.00	\$155.00	R X
5	Parking Sensor	1.00	\$252.00	\$252.00	su X
		<b>1</b>		<b>\$1,102.10</b>	
			Less 25%	\$275.53	
			<b>Sub Total 1</b>	<b>\$826.58</b>	
<b>B.</b>	<b>Labour</b>				
1	To knock and straighten necessary portion. To remove and			\$400.00	250
2	To check all neccessary lightings			\$60.00	40
3	To Install Parking Sensor			\$80.00	
4	To spray paint the affected areas			\$300.00	11 X
5	To Remove Upholstery			\$120.00	11 X
			<b>Total Labour</b>	<b>\$960.00</b>	
			<b>Total Repair Cost</b>	<b>\$1,786.58</b>	
	<b>* The above quoted are exclusive of GST.</b>				

Yours faithfully,

KAI  
f KT Garage Pte Ltd

*Not Authorized*  
*run noway*  
*1 day*  
*Whaph. After repair*  
*17/3/22*  
*P/P \$*  
*HP: 90096608*

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	231C
Vehicle Details	
Vehicle No.:	PC9145B
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1GD8455405
Chassis No.:	GDH2232002326
Maximum Power Output:	-
Open Market Value:	\$46,884.00
Original Registration Date:	13 Feb 2020
First Registration Date:	13 Feb 2020
Transfer Count:	1
Actual ARF Paid:	\$2,345.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,431.00
COE Rebate Amount:	\$18,685.00
Total Rebate Amount:	\$18,685.00

The information contained herein is correct as at 17 Mar 2022

OK