



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001389/Kvf3n2	
			Date: 23/02/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHC 4500L	Veh. Inspected	SML 5700M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/22/2023	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	14/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72001208	Colour	METALLIC GREY
	Odometer	139933 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	09/02/2022	Inspection Date	15/02/2022
	Survey held at	10, ANG MO KIO INDUSTRIAL PARK 2A #03-18		
	Repairer	MYCAR AUTO SERVICES		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	