

MYCAR PARTNERS PTE LTD
Company Reg No. 20187350M
10 Ang Mo Kio Industrial Park 2A
#03-18 AMK Autopoint
Singapore 568047
Tel: 97898985

Aspire 3

A314-32-C625

Not Authorized
11pm @ 1250hr
Returning After Paint
3 days

ESTIMATE

Menach Hong@LKKAuto.com

Date : 15/02/2022

SML5700M
HONDA SHUTTLE
DATE OF ACCIDENT 09/02/2022

DESCRIPTION	QUANTITY	RATE	AMOUNT	REMARKS
PARTS (LIST ITEM)				
Rear Boot	1	\$1,259.00	\$1,259.00	X
Rear Bumper	1	\$1,250.60	\$1,250.60	✓ 93650
			20%	
Parts subtotal			\$2,509.60	
LABOUR				
To remove the affected parts & fittings to commence repairs, panel beat & reshape the affected area		\$1,800.00	\$1,800.00	4001
Respray paint, putty on parts replaced & repaired area		\$1,600.00	\$1,600.00	4001
To remove & refix wiring & check all electrical components at damaged area for proper functions		\$600.00	\$600.00	151
To provide anti-rust treatment on affected areas		\$150.00	\$150.00	X
Labour subtotal			\$4,150.00	
Subtotal			\$6,659.60	

Total \$6,659.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: