



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22001391/Aqf3n2 Date: 15/03/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 8426Y	Veh. Inspected	SLM 1271S
	Policy No.		Coverage (\$)	0.00
	Claim No.	800SWAISCL2022 0058/SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	14/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	GK81101123	Colour	BLACK
	Odometer	96586 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	DAYTON	6 mm
	L/H Front Tyre	185/60 R15	DAYTON	6 mm
	R/H Rear Tyre	185/60 R15	DAYTON	6 mm
	L/H Rear Tyre	185/60 R15	DAYTON	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/02/2022	Inspection Date	14/02/2022
	Survey held at	1 KAKI BUKIT AVE 6, #01-15 AUTOBAY		
	Repairer	POLYMATH GARAGE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	