



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

Xiao Chen.

ESTIMATED REPAIR CHECKLIST

TO : ALLIANZ INSURANCE	VEHICLE REGISTRATION NO.: SLM1271S
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: HONDA / SHUTTLE
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: GK81101123
ACCIDENT DATE/TIME :	CONTACT PERSON : SEBASTIAN (97527592)

PARTS	QTY	PER UNIT	PRICES
1 FRONT BUMPER <i>torn</i>	1	\$ 1,050.00	\$ 1,050.00 ✓
2 FRONT BUMPER SIDE HOLDER RH <i>Damaged</i>	1	\$ 25.70	\$ 25.70 ✓
3 FRONT RH FENDER <i>Repair</i>	1	\$ 490.20	\$ 490.20 ✓
4 FRONT FENDER INNER SHIELD RH <i>Behind</i>	1	\$ 189.30	\$ 189.30 ✓
5 FRONT FENDER INNER PANEL RH <i>Repair</i>	1	\$ 520.40	\$ 520.40 ✓
6 HEADLAMP RH <i>cracked</i>	1	\$ 2,250.40	\$ 2,250.40 ✓
7 FRONT RH LOWER ARM	1	\$ 321.80	\$ 321.80 ✓
8 FRONT RH SHOCK ABSORBER <i>3 new</i>	1	\$ 345.10	\$ 345.10 ✓
9 FRONT RH KNUCKLE ARM	1	\$ 363.40	\$ 363.40 ✓
10 FRONT RH WHEEL HUB C/W BEARING <i>new</i>	1	\$ 294.20	\$ 294.20 ✓
		SUBTOTAL :	\$ 5,850.50
		LESS 20% :	\$ 1,170.10
		PARTS TOTAL :	\$ 4,680.40

3515.40
Less 20%: 2812.32

SPECIAL NETT	QTY	PER UNIT	PRICES
1 FRONT BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2 FRONT RH FENDER INNER SHIELD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00 ✓
3 FRONT RH WHEEL RIM <i>new</i>	1	\$ 180.00	\$ 180.00 ✓
4 FRONT RH WHEEL RIM COVER <i>cut</i>	1	\$ 100.00	\$ 100.00 ✓
5 FRONT RH TYRE <i>new</i>	1	\$ 250.00	\$ 250.00 ✓
		S/N TOTAL :	\$ 590.00

160

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 800.00	<i>400</i>
2 SPRAY PAINTING	\$ 800.00	<i>500</i>
3 WIRING	\$ 50.00	<i>30</i>
4 TO SPRAY TUFF COAT	\$ 150.00	<i>40</i>
5 TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>
6 TO REMOVE REAR UNDERCARRIAGE	\$ 320.00	<i>x.</i>
LABOR TOTAL :		\$ 2,270.00

1050



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

ESTIMATE REPORT

TOTAL PARTS COST:	\$ 5,270.40
TOTAL LABOUR COST:	\$ 2,270.00
TOTAL REPAIR COST:	\$ 7,540.40
PART BY PART / LUMP SUM:	
NO. OF REPAIR DAYS:	

SURVEYOR DETAILS

SURVEYOR NAME: Adnan Lj
CONTACT: _____
EMAIL: _____
DATE : _____
TIME : _____

total: 4022.32
L/S : 3.2K.
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: