

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001396/ATY3N2**Date:** 07/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00031642100
Claimant Vehicle No :	SCR6821C	Insured Vehicle No :	GBF8221X
Date of Loss:	10/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201029/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCR6821C	Engine No:	CVK086553
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF45KA107020
Reg. Date:	26/02/2020 (Man. Year: 2019)	Odometer:	27054 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,445.00	7,618.32	10,826.68	58.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,282.00	3,732.00	2,550.00	40.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,727.00	11,350.32	13,376.68	54.10
+ GST 7.00/7.00% (S\$)	1,730.89	794.52	936.37	54.10
Nett Amount (S\$)	26,457.89	12,144.84	14,313.05	54.10

INSPECTION

Date of Assignment:	14/02/2022	
Date Inspected:	14/02/2022	Inspected At: 55 UBI ROAD 1 . SINGAPORE 408699 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	143	AUDI A4 2.0 TFSI QU S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCR6821C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,188.00 FS	*3,188.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	276.00 FS	*276.00 FS
5	1		*REAR BUMPER TRIM	Cut	326.00 FS	*326.00 FS
6	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	260.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	92.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
9	2		*REAR BUMPER SEAL	Not Necessary	32.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	52.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP-LH/RH	Not Necessary	188.00 FS	*- FS
12	2		*PIN	Not Necessary	6.00 FS	*- FS
13	2		*REAR BUMPER GUIDE SECTION UPPER-LH/RH	Not Necessary	100.00 FS	*- FS
14	1		*AERIAL RETAINER-LH	Not Necessary	29.00 FS	*- FS
15	2		*TELEPHONE AERIAL	Not Necessary	384.00 FS	*- FS
16	1		*REAR PARKING AID SENSOR-INNER/OUTER (2 Pcs)	Damaged (1 Pc only)	244.00 FS	*63.42 FS
17	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
18	1		*REAR BUMPER WIRING SET	Not Necessary	745.00 FS	*- FS
19	2		*EXHAUST TAIL PIPE TRIM-LH/RH	Not Necessary	766.00 FS	*- FS
20	1		*REAR LID	Dented	3,497.00 FS	*3,497.00 FS
21	2		*REAR LID HINGE-LH/RH	Not Necessary	510.00 FS	*- FS
22	1		*REAR LID LOCK	Not Necessary	217.00 FS	*- FS
23	1		*REAR LID COVER CAP	Not Necessary	8.00 FS	*- FS
24	1		*REAR LID ATTACHMENT PARTS	Not Necessary	429.00 FS	*- FS
25	1		*REAR LID LOCK ACTUATOR	Not Necessary	1,478.00 FS	*- FS
26	1		*REAR LID LOCK STRIKER	Not Necessary	37.00 FS	*- FS
27	1		*ANTI-THEFT GUARD COVER	Not Necessary	71.00 FS	*- FS
28	1		*REAR LID FLAP GASKET	Not Necessary	229.00 FS	*- FS
29	1		*PACKING ADHESIVE	Necessary	21.00 FS	*20.90 FS
30	1		*AUDI EMBLEM	Necessary	144.00 FS	*143.50 FS
31	1		*A4 EMBLEM	Necessary	104.00 FS	*103.50 FS
32	2		*TAIL LIGHT-LH/RH	Not Necessary	2,270.00 FS	*- FS
33	2		*TAIL LIGHT TRIM-LH/RH	Not Necessary	68.00 FS	*- FS
34	2		*LICENCE PLATE LIGHT	Not Necessary	209.00 FS	*- FS
35	1		*REAR END PANEL TRIM	Not Necessary	185.00 FS	*- FS
36	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
37	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,445.00 7,618.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO REPAIR REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,400.00
4	TO RESPRAY REAR BUMPER,REAR LID HINGES AND REAR END PANELLING	New	3,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,282.00	3,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >