

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0100/2022/JT
DATE : 11-Feb-22
WIP : 11479

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/1/22

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Hi Adrian

4 days - ok - Johnny Boo

13-Apr-22

OWNER'S NAME : MR DEREK PAK GEK KWEE
ADDRESS : BLK 115 MARSILING RISE
#09-394
SINGAPORE 730115
TELEPHONE : HP +65 91193111
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : MT/00890724
VEHICLE NO : **SCR 6821 C**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 26/2/2020
ENGINE NO : CVK 086553
CHASSIS NO : WAUZZZF45KA107020
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-22
PLACE OF ACCIDENT : MARSILING ROAD U-TURN BEF
WOODLANDS CENTRE ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCR 6821 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER REAR LID;S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00	\$	1,400.00
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND REAR END PANELLING. <i>(Rear lid new Add \$100.00)</i>	\$	3,000.00	\$	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,282.00	\$	3,732.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCR 6821 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 3,188.00	\$	3,188.00
2	REAR BUMPER FIXING PARTS	1	\$ 480.00		
3	REAR BUMPER SECURING STRIP	1	\$ 249.00		
4	REAR BUMPER SPOILER - LH / RH	1	\$ 276.00	\$	276.00
5	REAR BUMPER TRIM	1	\$ 326.00	\$	326.00
6	REAR BUMPER BRACKET - LH / RH	2	\$ 260.00		
7	REAR LIGHT REFLECTOR - LH / RH	2	\$ 92.00		
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00		
9	REAR BUMPER SEAL	2	\$ 32.00		
10	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00		
11	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 188.00		
12	PIN	2	\$ 6.00		
13	REAR BUMPER GUIDE SECTION UPPER - LH / RH	2	\$ 100.00		
14	AERIAL RETAINER - LH	1	\$ 29.00		
15	TELEPHONE AERIAL	2	\$ 384.00		
16	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 244.00	\$	63.42
17	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00		
18	REAR BUMPER WIRING SET	1	\$ 745.00		
19	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 766.00		
20	REAR LID	1	\$ 3,497.00	\$	3,497.00
SUB TOTAL SPARE PARTS		:	\$ 12,055.00	\$	7,350.42

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCR 6821 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 7,350.42</i>
21	REAR LID HINGE - LH / RH	2	\$ 510.00	
22	REAR LID LOCK	1	\$ 217.00	
23	REAR LID COVER CAP	1	\$ 8.00	
24	REAR LID ATTACHMENT PARTS	1	\$ 429.00	
25	REAR LID LOCK ACTUATOR	1	\$ 1,478.00	
26	REAR LID LOCK STRIKER	1	\$ 37.00	
27	ANTI-THEFT GUARD COVER	1	\$ 71.00	
28	REAR LID FLAP GASKET	1	\$ 229.00	
29	PACKING ADHESIVE	1	\$ 21.00	<i>\$ 20.90</i>
30	AUDI EMBLEM	1	\$ 144.00	<i>\$ 143.50</i>
31	A4 EMBLEM	1	\$ 104.00	<i>\$ 103.50</i>
32	TAIL LIGHT - LH / RH	2	\$ 2,270.00	
33	TAIL LIGHT TRIM - LH / RH	2	\$ 68.00	
34	LICENCE PLATE LIGHT	2	\$ 209.00	
35	REAR END PANEL TRIM	1	\$ 185.00	
36	FRONT NO PLATE	S/N	\$ 60.00	
37	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 18,445.00	<i>\$ 7,618.32</i>
TOTAL LABOUR CHARGES		:	\$ 6,282.00	<i>\$ 3,732.00</i>
GRAND TOTAL		:	\$ 24,727.00	<i>\$ 11,350.32</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-12/04/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT