

Description of Circumstances of the Accident

on 21 Jan 2022 at about 18:25 I was driving along
 1 BIK 134 Jurong East Central to ward Jurong Town Hall.
 I was driving at lane two. The Bus PC7674D came out
 from the Bus stop and hit my left door and lost control
 and stop. I and my husband came down and check our
 car. The damage is bad. We waited for TP and Tow to
 come.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
 me




Driver's Signature (If driver is not the policyholder) / Date
 & Time



Witnessed by Reporting Centre
 Personnel

















HONDA AUTOMOBILE(THAILAND)CO.,LTD.
CHASSIS NO. MRHFC5650GT000508
ENGINE NO. R16B2-1600678
TEC G SA5 B-607M A