



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA22001400/Tnf3e2 Date: 04/08/2022  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBH 2792T	Veh. Inspected	SKS 5321K
Policy No.	BVFCB0013732102	Coverage (\$)	0.00
Claim No.	NSV2200022/SG	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	14/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MITSUBISHI LANCER 1.6	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JMYSRCY1AFU003996	Colour	SILVER
Odometer	192458 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	11/02/2022	Inspection Date	15/02/2022
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	