

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI22001401/RVY3N2**Date:** 08/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00154552100		
<b>Claimant Vehicle No :</b>	SGK6278K	<b>Insured Vehicle No :</b>	SKB9467L		
Date of Loss:	08/02/2022	Nature of Claim:	TP	Claim No:	SNM22D200951/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGK6278K</b>		Engine No:	MR20884987B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR (A)		Chassis No:	JN1JANT32Z0002260
Reg. Date:	28/07/2016 (Man. Year: 2016)		Odometer:	52844 km
Colour:	White			
Engine Capacity:	1997 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R18	Rear Tyre Size:	225/60R18
Front Left Side:	LAUFENN 6 mm	Rear Left Side:	LAUFENN 6 mm
Front Right Side:	LAUFENN 6 mm	Rear Right Side:	LAUFENN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	11/02/2022	
Date Inspected:	14/02/2022 Inspected At:	One Zone Autopmotive Llp (HQ) 5 YISHUN INDUSTRIAL STREET #01-20 NORTH SPRING BIZHUB SINGAPORE Singapore 768161
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00  
-\$2,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 08 Mar 2022)

**Parts:**            M1-SUV    NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGK6278K)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**