

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimm@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : ZAHARIN BIN ABUZAR  
 588A ANG MO KIO ST 52  
 #04-207  
 SINGAPORE 561588

Estimate No: MCI902469  
 Date: 14 Feb 2022  
 Policy No: P10423112R00  
 Veh Reg No: SJD5756E  
 Make/Model: TOYOTA RUSH 1.5X A

ATTN:  
 Your Ref No: SJD5756E  
 Claim Type: Third Party → China  
 Accident Date: 06/02/2022  
 TP Veh Reg No: SKL9193Z

Loc  
2pm

## Estimate Repair Cost to Vehicle No :SJD5756E

Description	Quantity	List Price	Amount
		SS	SS
<b>SPARE PARTS</b>			
1 TAILGATE <i>bt</i>	1 PC	841.90 ✓	
2 TAILGATE RUSH LOGO <i>me</i>	1 PC	92.70 <i>69.50</i>	
3 TAILGATE RUBBER <i>rec</i>	1 PC	270.90 <i>219.00</i>	
4 TAILGATE INNER LOCK <i>Xan</i>	1 PC	217.60 X	
5 TAILGATE INNER TRIMBOARD <i>? Xan</i>	1 PC	489.70 X	
6 TAILGATE SPARE WHEEL COVER OUTER <i>ca</i>	1 PC	1,704.80 <i>1508</i>	
7 TAILGATE SPARE WHEEL COVER INNER <i>? ca</i>	1 PC	583.70 <i>335.70 as per supplier inv</i>	
8 TAILGATE SPARE WHEEL COVER LOCK LH & RH <i>Xan</i>	2 PC	540.20 X	
9 REAR BUMPER <i>de</i>	1 PC	880.80 ✓	
10 REAR BUMPER SIDE RETIANER LH & RH <i>ca / 1pc @ 20.10</i>	2 PC	140.20 <i>70.10</i>	
11 REAR BUMPER CLIPS <i>ca</i>	15 PC	82.50 <i>40</i>	
12 REAR BUMPER TOW COVER RH <i>ms</i>	1 PC	45.10 ✓	
13 REAR END PANEL <i>? Xan</i>	1 PC	317.80 X	
14 REAR END PANEL TOP GARNISH <i>? Xan</i>	1 PC	127.60 X	
		6,087.50	
	Less 25%	1,521.88	4,565.63
<b>Special Nett</b>			
15 NUMBER PLATE <i>bt</i>	1 PC	35.00 ✓	
16 REVERSE SENSOR <i>? an</i>	1 SET	200.00 ✓	
17 INNER SEAL <i>an</i>	1 PC	20.00 ✓	
18 WINDSCREEN SEALANT <i>an</i>	1 PC	40.00 ✓	
19 SPARE TYRE - CHECK PRICE	1 PC	0.0000	
		295.00	295.00
<b>LABOUR</b>			
20 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 <i>Xan</i>	
21 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00 ✓	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00 <i>60</i>	
23 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR FLOOR PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00 <i>500</i>	
24 TO SPRAY TAILGATE, SPARE TYRE COVER, REAR BUMPER, END PANEL, FLOOR PANEL.	1 PC	800.00 <i>600</i>	
		1,840.00	1,840.00

*Zila*  
 Ah Lim Motor Company

4258.10  
 259  
 3193.57

1280

UD Trucks Singapore (Pte.) Ltd

Date/Time

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : ZAHARIN BIN ABUZAR  
588A ANG MO KIO ST 52  
#04-207  
SINGAPORE 561588

Estimate No: MC1902469  
Date: 07 Mar 2022  
Policy No: P10423112R00  
Veh Reg No: SJD5756E  
Make/Model: TOYOTA RUSH 1.5X A

ATTN:

Your Ref No: SNM22D200880  
Claim Type: Third Party  
Accident Date: 06/02/2022  
TP Veh Reg No: SKL9193Z

## Estimate Repair Cost to Vehicle No :SJD5756E

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 TAILGATE SPARE WHEEL HOLDER BRACKET <i>bf</i>	1 PC	273.40	
2 TAILGATE SPARE WHEEL HOLDER CLIP <i>ka</i>	1 PC	12.10	
		285.50	
	Less 25%	71.38	214.13
	Total		S\$ 214.13
	GST Amount		S\$ 14.99
	Total Amount Payable		S\$ 229.11

The above vehicle was surveyed by RASUL - LKK AUTO on 15/02/2022

For AH LIM MOTOR COMPANY

\* Resurvey by rasul.  
08/02/22 2pm.  
requested for P&P

AUTHORISED SIGNATURE

\* email before print photos & tail gate spare wheel cover inner (order 3-4 weeks)

3193.57  
295.00  
1280.00  
214.13

4982.70

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : ZAHARIN BIN ABUZAR  
588A ANG MO KIO ST 52  
#04-207  
SINGAPORE 561588

Estimate No: MC1902469  
Date: 14 Feb 2022  
Policy No: P10423112R00  
Veh Reg No: SJD5756E  
Make/Model: TOYOTA RUSH 1.5X A

ATTN:  
Your Ref No: SJD5756E  
Claim Type: Third Party  
Accident Date: 06/02/2022  
TP Veh Reg No: SKL9193Z

## Estimate Repair Cost to Vehicle No :SJD5756E

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 6,700.63
		Add GST @ 7%	469.04
		Total Amount Payable	SS 7,169.67

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED SIXTY NINE AND CENTS SIXTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY

Ah Lim Motor Company

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid  
Hp 90010068  
5 days  
48 P/P  
15/02/22 P1410  
Resy after repair