

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22001421/TVF3N2**Date:** 18/03/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SHC8780T**Insured Vehicle No :** GBG4618G

Date of Loss: 13/02/2022

Nature of Claim: TP

Claim No: DM22HO00214

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC8780T**

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZRS044836

Reg. Date: 30/05/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU503557533

Colour: Blue

Odometer: 622444 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,734.82	511.71	7,223.11	93.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	600.00	890.00	59.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,224.82	1,111.71	8,113.11	87.95
Approved Total (Overridden) (S\$)		900.00		
(S\$)	9,224.82	900.00	8,324.82	90.24
+ GST 7.00/7.00% (S\$)	645.74	63.00	582.74	90.24
Nett Amount (S\$)	9,870.56	963.00	8,907.56	90.24

INSPECTION

Date of Assignment: 14/02/2022 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 15/02/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8780T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	499.90 FL	*499.90 FL
2	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	920.00 FL	*- FL
4	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	82.30 FL	*- FL
5	1		*FRT BUMPER SUPPORT LH	Not Necessary	81.70 FL	*- FL
6	1		*HEAD LAMP PANEL LH	Not Necessary	240.10 FL	*- FL
7	1		*HEADLAMP LH	Not Necessary	2,735.28 FL	*- FL
8	1		*FRT BUMPER REINFORCEMENT ABSORBER LH	Not Necessary	115.70 FL	*- FL
9	1		*FRT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	*- FL
10	1		*FRT BUMPER LOWER REINFORCEMENT	Not Necessary	364.20 FL	*- FL
11	1		*FRT BUMPER SPONGE	Not Necessary	78.80 FL	*- FL
12	1		*RADIATOR GRILLE	Not Necessary	438.00 FL	*- FL
13	1		*FRT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
14	1		*FRT BUMPER TOWING COVER LH	Cut	28.38 FL	*28.38 FL
15	1		*RADIATOR SUPPORT LH	Not Necessary	234.70 FL	*- FL
16	1		*RADIATOR ASSY	Not Necessary	1,841.80 FL	*- FL
17	1		*CONDENSER ASSY	Not Necessary	1,336.60 FL	*- FL
18	1		*COOLANT	Not Necessary	90.00 FL	*- FL
19	1		*FRT NUMBER PLATE EXTENSION	Deformed	99.00 F	*99.00 F
20	1		*FRT NUMBER PLATE WITH TRIM COVER	Not Necessary	55.00 F	*- F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	10,261.76	649.28
- List Item Discount on L Items 25.00/25.00% (\$)	2,526.94	137.57
Total Parts (\$)	7,734.82	511.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,050.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK ALL LIGHTING	New	80.00	0.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,490.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >