

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K GST No : 200600989k

MSIG

Motorcar Claim Department
Attn Claim Officer

Estimate Repair

Date : 14/02/2022

Accident Involving SKL9097T & SGM1611D On 04/02/2022 At Open Carpark

SKL9097T

Mercedes CLA200

Item	Descriptions	Amount
1	Rear Left Door	\$ 1,714.00 ✓
2	Rear Left Door Lock	\$ 315.65 X
3	Rear Left Door Glass Chrome	\$ 200.09 X
4	Rear Left Door Weather Strips	\$ 265.36 ✓
5	Rear Left Fender 2800 117 630 0121	\$ 2,889.00 ✓
6	Rear Left Outer Parking Sensor	\$ 202.23 X
7	Rear Left Wheel Hub Bearing	\$ 354.17 X
8	Rear Left Knuckle Arm	\$ 425.24 X
9	Rear Left Upper Arm	\$ 163.71 X
10	Rear Left Lower Arm	\$ 154.08 X

Total For Parts (Less 10%) \$ 7,683.53

S/N Item (s)

1	RL Sport Rim → 108	\$ 954.00 ✓
2	Bumper Clips - 1 Set	\$ 35.00 ✓

Total For S/N \$ 989.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	\$ 1,500.00 800l
2	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 1,200.00 750l
3	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 260.00 X
4	Remove & Refix RR Undercarriage Parts To Check	\$ 60.00 ✓
5	Computerise 4 Wheels Alignment	\$ 250.00 100l
6	To Remove & Refix Floor & Roof Rining, Seat etc To Facilitate Repair	\$ 150.00 60l
7	Computerise Reprogramming Parking Sensor & Rear Left Door False Memory	\$ 50.00 20l
8	Check Wiring, Lighting System For Proper Function	\$ 100.00 60l
	Cavity Preservation On All Affected Areas	

\$ 3,570.00

Total For Parts & Labour \$ 12,242.53

Ready Auto Care Pte Ltd

Sulynn - 96606551

No Of Days For Repair 8 Days

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: