

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

15/02/2022 12:33

JOB-NO: 50113949

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522VEHICLE DETAILS

LICENSE NO: SHA9457G

TRANS: AUTO

CHASSIS: KMHC851CVJU103631

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEJU046922

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00	500 /	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30 /	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	400.00	0.00	400.00	X	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	300.00	0.00	300.00	30 /	Y	
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	150.00	0.00	150.00	80 /	Y	
6 TO READJUST AND REALIGN HEADLAMP AIM	1.00	120.00	0.00	120.00	30 /	Y	
7 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	180.00	0.00	180.00	X	Y	
8 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	280.00	0.00	280.00	X	Y	
9 TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO FACILITATE BODYWORK REPAIR	1.00	350.00	0.00	350.00	X	Y	
10 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	200 /	Y	
11 TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	250.00	0.00	250.00	X	Y	
12 TO RESPRAY FRONT BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	X	Y	
13 TO RESPRAY FRONT BUMPER MOULDING	1.00	250.00	0.00	250.00	50 /	Y	
14 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00	200 /	Y	
15 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	X	Y	
16 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200 /	Y	
17 TO RESPRAY FRONT SIDE MIRROR	1.00	250.00	0.00	250.00	50 /	Y	
18 TO RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00	X	Y	
TOTAL:		5,600.00	0.00	5,600.00			
<u>MATERIALS</u>							
1 FRONT BUMPER COVER / BR	1.00	430.90	86.18	344.72	L	Y	
2 FRONT RH BUMPER RETAINER / BR	1.00	28.00	5.60	22.40	L	Y	
3 FRONT RH BUMPER SIDE SUPPORT BRACKET X NN	1.00	12.00	2.40	9.60	L	Y	
4 FRONT BUMPER ENERGY ABSORBER X NN	1.00	86.90	17.38	69.52	L	Y	
5 FRONT BUMPER REINFORCEMENT X NN	1.00	1,075.10	215.02	860.08	L	Y	

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
6 FRONT RH BUMPER MOULDING	1.00	93.00	18.60	74.40	L	Y	
7 FRONT RH FOG LAMP	1.00	642.50	128.50	514.00	L	Y	
8 FRONT RH BUMPER AIR CURTAIN DUCT	1.00	43.90	8.78	35.12	L	Y	
9 FRONT BUMPER UPPER CENTER MOULDING	1.00	284.90	56.98	227.92	L	Y	
10 FRONT BUMPER UNDERTRAY COVER	1.00	469.40	93.88	375.52	L	Y	
11 FRONT RH HEADLAMP	1.00	2,110.30	422.06	1,688.24	L	Y	
12 FRONT END MODULE CARRIER	1.00	949.30	189.86	759.44	L	Y	
13 FRONT RH FENDER PANEL	1.00	588.80	117.76	471.04	L	Y	
14 FRONT RH FENDER LINER	1.00	114.70	22.94	91.76	L	Y	
15 FRONT RH FENDER EMBLEM	1.00	26.60	5.32	21.28	L	Y	
16 FRONT RH SIDE MIRROR ASSY	1.00	1,054.60	210.92	843.68	L	Y	
17 FRONT RH DOOR PANEL	1.00	1,978.00	395.60	1,582.40	L	Y	
18 FRONT RH TYRE RIM	1.00	1,091.50	218.30	873.20	L	Y	
19 FRONT BUMPER LOWER GRILLE COVER	1.00	186.90	37.38	149.52	L	Y	
20 FRONT BUMPER LOWER MOULDING	1.00	44.00	8.80	35.20	L	Y	
21 SIDE SKIRT RH	1.00	315.10	63.02	252.08	L	Y	
22 FRONT RH KNUCKLE ARM	1.00	363.60	72.72	290.88	L	Y	
23 FRONT RH KNUCKLE HUB + BEARING	1.00	452.80	90.56	362.24	L	Y	
24 FRONT RH LOWER ARM	1.00	296.80	59.36	237.44	L	Y	
25 FRONT RH SHOCK ABSORBER	1.00	372.50	74.50	298.00	L	Y	
26 FRONT RH STABILIZER LINK	1.00	74.90	14.98	59.92	L	Y	
27 WIPER RESERVOIR	1.00	150.80	30.16	120.64	L	Y	
28 FRONT BUMPER CLIP SET	1.00	75.00	0.00	75.00	S	Y	
29 FRONT BUMPER RIVET SET	1.00	65.00	0.00	65.00	S	Y	
30 FRONT BUMPER UNDERTRAY COVER CLIP	1.00	60.00	0.00	60.00	S	Y	
31 FRONT BUMPER MOULDING CLIP SET	1.00	55.00	0.00	55.00	S	Y	
32 FRONT FENDER LINER CLIP SET	1.00	65.00	0.00	65.00	S	Y	
33 FRONT FENDER PANEL ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
34 FRONT DOOR ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
35 SIDE SKIRT ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
36 SIDE SKIRT CLIP SET	1.00	65.00	0.00	65.00	S	Y	
37 RADIATOR COOLANT 4L	1.00	150.00	0.00	150.00	S	Y	
38 FRONT TYRE 195/65/15	1.00	300.00	0.00	300.00	S	Y	
39 FRONT DOOR "COMFORT DELGRO" STICKER	1.00	150.00	0.00	150.00	S	Y	
TOTAL:		15,072.80	,667.56	12,405.24			

TOTAL PARTS & LABOUR :

20,672.80

2,667.56

18,005.24

EXCESS/LOADING:\$\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISID IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

LKK Auto Consultants hence notify

the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

G-STAR-WI-ET-001-02-Rev00