



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0101/2022/JT
DATE : 14-Feb-22
WIP : 11584

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 15/2/22

YOUR INSURED VEH NO : SMA 3003 M

NTUC INCOME INSURANCE CO - CLAIMS DEPARTMENT

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Steve
5 days - ok - Johnny Boo
3-Jun-22

OWNER'S NAME : MS TAN MEI LI (CHEN MEILI) @ SARAH MICHELLE TAN
ADDRESS : BLK 1B CANTOMENT ROAD
#33-23
SINGAPORE 085201
TELEPHONE : HP +65 96790115
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900080993-02
VEHICLE NO : **SMJ 9986 P**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 27/3/2019
ENGINE NO : CVK 077095
CHASSIS NO : WAUZZZF41KA041047
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Feb-22
PLACE OF ACCIDENT : ALONG NEIL ROAD TOWARDS KG
BAHRU ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 9986 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRASNFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,400.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 1,500.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,402.00	\$ 3,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 9986 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,787.00	\$	1,787.00
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00		
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00		
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 409.00		
7	FRONT PARKING AID SENSOR - INNER / OUTER	1	\$ 244.00		
8	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
9	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$	40.30
10	FRONT FENDER - RH	1	\$ 861.00	\$	861.00
11	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00		
12	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	\$	80.30
13	FRONT FENDER BRACKET - RH	1	\$ 41.00		
14	POP RIVET	6	\$ 23.00	\$	22.80
15	FRONT FENDER BRACE - RH	1	\$ 132.00	\$	131.50
16	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00		
17	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	\$	262.00
18	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 219.00		
19	FRONT WHEEL SPOILER	1	\$ 82.00		
20	FRONT FENDER END PLATE - RH	1	\$ 40.00		
SUB TOTAL SPARE PARTS		:	\$ 5,515.00	\$	3,184.90

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 9986 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 3,184.90</i>
21	FRONT FENDER STONE CHIP GUARD - RH	1	\$ 57.00	
22	HEADLIGHT - RH	1	\$ 7,693.00	
23	LIFT CYLINDER - RH	1	\$ 231.00	
24	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
25	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	
26	FRONT FENDER LEDGE COVER SHORT - RH	1	\$ 26.00	
27	RHS FRONT RIM	S/N	\$ 1,278.00	
28	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 15,292.00	\$ 3,184.90
TOTAL LABOUR CHARGES			\$ 5,402.00	\$ 3,852.00
GRAND TOTAL			\$ 20,694.00	\$ 7,036.90

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-27/04/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT