

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS/INC22001431/Evf3n2	
	73 BRAS BASAH R #05-01 NTUC TRAI 189556	COAD DE UNION HOUSESINGAPORE	Date:	08/03/2022	
	ATTN: JESSIE WO		Code	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 7623Y	Veh. Inspected	SHD 2568A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1161381-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	15/02/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA CAMRY	c.c	2487	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	AXVH701034196	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	DUNLOP	5 mm	
	L/H Front Tyre	215/55 R17	DUNLOP	5 mm	
	R/H Rear Tyre	215/55 R17	DUNLOP	5 mm	
	L/H Rear Tyre	215/55 R17	DUNLOP	5 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION .				
	DAMAGES SEE DE	IAGES SEE DETAILS.			
5.					
	Accident Date	10/02/2022	Inspect Date / Time	15/02/2022 (12:20 PM)	
	Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD			
		6 BENOI PLACE SINGAPORE 629927			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days			