



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 11.02.2022

NTUC Income Insurance Co-operative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn: Motor Claims Dept

RE: ESTIMATE COST TO SHD2568A TOYOTA CAMRY HYBRID 2.5G CVT (2019)

To Supply

1) 1pc	front bumper / BR	\$	972.00 874 /
2) 1pc	front bumper right side retainer / BR	\$	55.60 /
3) 1pc	front bumper left side retainer / BR	\$	55.60 /
4) 1pc	front bumper reinforcement / DD	\$	459.00 /
6) 1pc	front bumper sponge / BR	\$	115.00 /
7) 1pc	front bumper center lower grille sub assy / BR	\$	750.00 675 /
8) 1pc	front radiator grille assy / X NN	\$	950.00 X
10) 1pc	right radiator grille side moulding 53123-33050 / X NN	\$	72.00 X
11) 1pc	engine lower cover 51441-33220 / BR	\$	580.00 522 /
12) 1pc	right head lamp assy / BR	\$	3,500.00 2890.40 /
13) 1pc	right head lamp lower bracket / X NN	\$	122.50 X
14) 1pc	left head lamp / BR	\$	3,500.00 2890.40 /
15) 1pc	right fog lamp / X NN	\$	516.00 X
16) 1pc	left fog lamp / BR	\$	516.00 353.80 /
17) 1pc	front bumper right ultrasonic sensor / BR	\$	420.00 /
18) 1pc	front bumper left ultrasonic sensor / BR	\$	420.00 /
19) 1pc	front bumper ultrasonic sensor wire / X NN	\$	355.00 X
20) 1pc	right front fender cowling / X NN	\$	195.00 X
21) 1pc	left front fender cowling / CRW	\$	240.00 /
* 22) 1pc	left front shock absorber / BT	\$	595.00 /
* 23) 1pc	left front nuckle arm / BT	\$	586.00 /
* 24) 1pc	left front driver shaft / BT	\$	1,650.00 1298.50 /
25) 1pc	left front lower arm / BT	\$	459.00 /
26) 1pc	left front lower ball joint / BT	\$	197.00 /
* 27) 1pc	left rear shock shock absorber / X NN	\$	227.00 X

*28) 1pc	left rear axle carrier sub assy 42305-33050	\$	850.00✓
*29) 1pc	left rear suspension arm assy 48710-33160	\$	317.00 225✓
30) 1pc	left rear trailing arm assy 48780-33090	\$	280.00 x
31) 1pc	rear bumper	\$	980.00 x
32) 1pc	rear bumper lower cover	\$	366.58 ✓

14,547.88
-25%
10,910.91

Sub total parts	\$	20,301.28
Less: 25% discount	\$	(5,075.32)
Sub total parts	\$	15,225.96

To supply S. Nett Parts

1) 1pc	left front tyre sport rim	\$	3,140.00 X
2) 1pc	left front tyre	\$	280.00 X
3) 1pc	left rear tyre sport rim	\$	3,140.00 X
4) 1pc	right front sport rim	\$	3,140.00 X
5) 1set	front bumper clip	\$	30.00 ✓
6) 1set	front grille clip	\$	15.00 X
7) 1set	left front fender clip	\$	20.00 ✓
8) 1set	left rear fender clip	\$	20.00 X

Sub total S. Nett parts \$ 9,785.00

L/charges

1) Towing charges with invoice	\$	80.00 ✓
2) To remove front right, front left & rear left tyres, sport rim. Replace tyre rim, balance left front tyre	\$	180.00 40
3) To computerise wheel alignment	\$	80.00 ✓
4) To remove & replace front right & left ultrasonic sensor check wiring	\$	100.00 30
5) To remove left front suspension, undercarriage parts, replace necessary parts	\$	300.00 250
6) To remove left rear suspension, undercarriage parts, replace necessary parts	\$	280.00 200
7) To knock radiator support panel. right wheel house panel. remove front bumper, front grille. lower grille. reinforcement. sponge. repair front bonnet hinges. bonnet lock hook. replace the above parts. Adjust front bonnet, left & right fender & front bumper	\$	900.00 600
8) To putty, respray painting front bumper. right wheel house panel, support	\$	900.00 800

2480

panel, rear bumper

Sub total L/charges	\$	2,820.00
Estimated Grand Total	\$	27,830.96

= 13,440.91

33,195.53

SUPP 1 = 3258.75

SUPP 2 = 1511.40

18,211.06



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Supp. 1

Date: 16.02.2022

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01

NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

**RE: SUPPLEMENTARY COST TO SHD2568A TOYOTA CAMRY HYBRID 2.5G CVT
(Year 2019)**

To Supply

1) 1pc	No. 2 engine under cover 51442-33220	BR	\$	312.00 ✓
2) 1pc	left front floor cover 58166-33030	BR	\$	595.00 530 ✓
3) 1pc	left rear brake disc 42431-78010	BR	\$	400.00 ✓
4) 1pc	left rear axle hub & bearing assy 42450-33080	Jammed	\$	920.00 821.50 ✓
5) 1pc	left rear suspension arm assy 48730-33160	X Repaired Item	\$	225.00 X
6) 1pc	left rear disc brake dust cover assy 47804-33010	BT	\$	65.00 ✓
7) 1pc	left parking actuator assy 46310-33010	BR	\$	1330.00 ✓
8) 1pc	rear disc pad	M	\$	180.00 X
9) 1pc	left front stabilizer link assy 48820-33090	BT	\$	159.00 ✓
10) 1pc	left front shock absorber mounting 48609-33260	BT	\$	150.00 ✓
11) 1pc	left front axle hub assy 43550-33020	Jammed	\$	577.50 ✓

Sub total parts \$ 4,913.50

Less: 25% discount \$ (1,228.38)

\$ 3,685.12

Steve (LKK)
16/2/21

4345
-25%
3258.75



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 16.02.2022

Supp. 2

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01

NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

**RE: SUPPLEMENTARY COST TO SHD2568A TOYOTA CAMRY HYBRID 2.5G CVT
(Year 2019)**

To Supply

1) 1pc	front right bonnet hinge 53410-33300	BT	\$	68.60	/
2) 1pc	front left bonnet hinges 53420-33300	BT	\$	68.60	/
3) 1pc	radiator top panel 53205-33901	DD	\$	350.00	280 /
4) 1pc	support side panel 53202-33903	DD	\$	280.00	243 /
5) 1pc	support side panel 53203-33902	DD	\$	280.00	243 /
6) 1pc	lower member 57104-33080	DD	\$	280.00	/
7) 1pc	towing cover 53128-33040	MIS	\$	26.00	/
8) 1pc	shuttle radiator 53019-33010	(grille inner guard) - BR	\$	560.00	480 /
9) 1pc	front bumper extension - 52103-33010	(LH) - DD	\$	210.00	/
10) 1pc	clamp piping 88718-1E150	MIS	\$	20.00	/
11) 1pc	left sensor retainer 89348-12070-A3	BR	\$	48.00	/
12) 1pc	right sensor retainer 89348-12140-A3	BR	\$	48.00	/

Sub total parts	\$	2,239.20
Less: 25% discount	\$	(559.75)
Estimated Total	\$	1,679.45

2015.20
-25%
1511.40