



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 08.02.2022

NTUC Income Insurance Co-operative Ltd  
73 Bras Basah Road #05-01  
NTUC Trade Union House  
Singapore 189556

Steve (LKK)

15/2/22, 12:00p

W R  
L5  
M ALy  
4 dy

Attn: Motor Claims Dept

**RE: ESTIMATED COST OF REPAIR TO VEHICLE SLV4852Z TOYOTA HARRIER 2.0**  
(REGISTRATION DATE: 29.12.2017)

## To supply

|         |                           |      |    |          |   |
|---------|---------------------------|------|----|----------|---|
| 1 ) 1pc | Right rear door           | / DO | \$ | 1,319.00 | — |
| 2 ) 1pc | Right rear fender         | X R  | \$ | 1,211.00 |   |
| 3 ) 1pc | Right rear fender cowling | X nn | \$ | 185.00   |   |
| 4 ) 1pc | Rear bumper               | X R  | \$ | 1,381.00 |   |

|                    |    |            |        |
|--------------------|----|------------|--------|
| Sub total Parts    | \$ | 4,096.00   |        |
| Less: 25% discount | \$ | (1,024.00) | 984.25 |
|                    | \$ | 3,072.00   |        |

## To supply S.Nett Parts

|          |                                 |      |    |       |   |
|----------|---------------------------------|------|----|-------|---|
| 1 ) 1set | Rear bumper clips               | / MC | \$ | 30.00 | / |
| 2 ) 1set | Right rear fender cowling clips | X nn | \$ | 20.00 | X |
|          |                                 |      | \$ | 50.00 |   |

## L/charges

|     |                                                                                                                                              |        |        |
|-----|----------------------------------------------------------------------------------------------------------------------------------------------|--------|--------|
| 1 ) | To tuff kote affected portion.                                                                                                               | \$ 30  | 50.00  |
| 2 ) | To transfer rightr rear door trim board, handle, mechanism parts & etc.                                                                      | \$ 850 | 60.00  |
| 3 ) | To cut / welding right rear fender. Remove rear bumper & right rear door. Replace the above necessary parts. Align & adjust right rear door. | \$ 500 | 700.00 |
| 4 ) | To putty, respray painting rear bumper, right rear fender & right rear                                                                       | \$ 600 | 700.00 |

2199.25

L/S - 1759.40  
= 1750

door's inlet & outer. To polish.

|                       |    |          |
|-----------------------|----|----------|
| Sub total L/charges   | \$ | 1,510.00 |
| Estimated Grand Total | \$ | 4,632.00 |

Prepared by: Chrissy

LKK Auto Consultants hereby notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date: