

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22001433/VTF3N2**Date:** 17/03/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV002248
Claimant Vehicle No :	SHC2441L	Insured Vehicle No :	SBD282H
Date of Loss:	13/02/2022	Nature of Claim:	TP
		Claim No:	M2200777

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2441L	Engine No:	2ZR2C05253
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU603079753
Reg. Date:	01/04/2019 (Man. Year: 2018)	Odometer:	251334 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,402.95	1,149.00	253.95	18.10
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	430.00	220.00	210.00	48.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,843.95	1,380.00	463.95	25.16
+ GST 7.00/7.00% (S\$)	129.08	96.60	32.48	25.16
Nett Amount (S\$)	1,973.03	1,476.60	496.43	25.16

INSPECTION

Date of Assignment:	15/02/2022	
Date Inspected:	14/02/2022	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	1.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,379.99

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2441L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*WING MIRROR RH	Broken	1,728.70 FL	-	*1,390.10 FL
2	1		*WING MIRROR OUTER COVER RH	Missing	141.90 FL	-	*141.90 FL
					Sub Total (S\$)	1,870.60	1,532.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	467.65	383.00
					Total Parts (S\$)	1,402.95	1,149.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	200.00	100.00
2	SPRAY PAINTING	New	200.00	100.00
3	CHECK WIRING	New	30.00	20.00
Gross Labour Cost (\$\$)			430.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >