

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

Not Authorized
11/12/21
Resurvey After Paint
5 days

INS: AXA Insurance Pte Ltd
 OWNER: TEO HENG LAM
 Registration no. : SLX 9986 C / HONDA SHUTTLE HYBRID 1.5 AUTO
 Accident date: 28/12/2021
 Date : 14-Feb-22 Quotation No. : 28129986

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Rear Tail Gate	R 1,193.10 ✓
2	1	Rear Tail Gate inner lock	286.80 ✓
3	1	Rear Tail Gate inner trim board	my cam 285.00 ✓
4	1	Rear Tail Gate rubber	Delidit 135.50 ✓
5	1	Rear Bumper	R 988.60 ✓
6	1 set	Rear Bumper Bracket \$58 X 2	in MLD 116.00 X
7	2 Pc	Rear Bumper Side Retainer \$65 X 2	no dis 130.00 ✓
8	1	Rear End Panel	R 701.40 ✓
9	1	Rear End Panel Top Garnish	my dis 185.30 ✓
10	1	Rear Spare Tyre Panel	R 1,560.40 X
11	1	Rear Spare Tyre Cover	in 285.40 X
12	1	Rear Tool Board Assy	cm 485.00 ✓
13	2	Rear Reflector Lamp \$115 X 2	in 230.00 X
14	1	Rear Tow Cover	in 38.50 X
			\$ 6,621.00
LESS:			20% \$ 1,324.20
			<u>\$ 5,296.80</u>

SPECIAL NETT ITEMS

- | | | |
|----|---|-------------------------------|
| 1 | 1 | Rear number plate |
| 2 | 1 | Rear reverse sensor |
| 4 | 1 | Rear end panel sealant |
| 5 | 1 | Rear windscreen glass sealant |
| 6 | 1 | Rear camera |
| 7 | 1 | Rear floor panel sealant |
| 8 | 1 | Honda Logo |
| 9 | 1 | Shuttle Emblem |
| 10 | 1 | Hybrid Emblem |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Not 50.00 *455m*
Rel 300.00 *200m*
na 84.00 *30m*
na 80.00 *40m*
in 350.00 X
na 80.00 X
na 58.40 —
na 85.70 —
na 105.00 —

\$ 1,193.10

LABOUR & MISC CHARGES

- | | | | |
|---|---|----------|------------|
| 1 | To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. | 1,200.00 | <i>700</i> |
| 2 | Supply spray paint material and necessary items | 900.00 | <i>660</i> |
| 3 | To disconnect wire / Replace / Rear Camera electrical component to facilitate repairs, reconnect and check functions. | 220.00 | <i>70</i> |
| 4 | To replace tailgate, check and re-adjust the close gap and alignment and water seepage test. | 200.00 | <i>60</i> |
| 6 | To remove and refit rear windscreen glass to facilitate repair. | 180.00 | <i>120</i> |

TOTAL

\$ 2,700.00

Total Parts and Labour Cost of Repair

\$ 9,189.90