

ASS. REC. BY: Steve REF: CS/ASM22001437/y3 ^E

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SNC 9459U
 Policy No. _____
 Claims No. S2M03T61
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: MBL 9859 Yr Regn: 5/7/07
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha Legend c.c. 110
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: N/A T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PMYKE 0658700 8870
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 70/90-17
 R: 80/90-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 10/2/92 D.O.I. 16/2/92
 Survey held at Kim Mack
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/3/22	Steve informed LS \$1550 (red 816, 34%)

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 21/3/22-typist

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Report Format: TP

Lump Sum / T.B. (\$ 1550)

5/2/22

MBL 9859

(TP-Polic)-78 Wing — \$45. (Towing) / MC

Front Fork Repair \$150 —

Front Mudguard — \$78 — / BR

Front No'plate — \$30 — / MC

Brake lever (R) — \$28. / CUT

Mirror R/L \$58. / CUT 29 / (R4)

Handle Bar — \$98. / BT

Reflector R/L \$48. / MIS

Handle Grip — \$38. / TN

Head light Assy \$185. / CUT

Head Cowling — \$78. / CUT

✓ (R/L) Front Fork cover \$76 — (RH) / BR

R/L Front Side Failing \$170. / CUT

Brake Pedal — \$78. / BT

Assy. Front Foot Rest Bar \$95. / BT

AIR PIPE Pullstem \$295. / ON

R/L Rear Foot Bracket \$150. / BR

Rear Foot Rest R/L \$48. / CUT

R/L Rear Side Side Cover \$180 — / CUT

Rear Katong Assy ^{RH} (Absorber) — \$180. / BT

Rear Seat Bar — \$78. / CAT

labour — \$180 150 /

\$236

Steve (LKK)

16/2/22, 11.40a

83228813

WM RL

3 djs

L/S

MALAY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: