

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAKASAGO INTERNATIONAL (S) PTE LTD
5 SUNVIEW ROAD
SINGAPORE 627616

TP Chinn.
Denise.

Contact : 67791077 97506590

TAX INVOICE

Repair Code : CLM17097

Date in : 14/02/2022

Vehicle Num. : GBG923B

Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Chassis/Eng# : VSKYBAM20Z0141642/K9KC400D056519

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE INTERCOOLER HOSE <i>cut</i>	1	236.00	✓ 236.00
FRONT AIR GUIDE GARNISH (BOTTON) L/R <i>new</i>	2	45.00	✗ 90.00
FRONT AIR GUIDE GARNISH (TOP) L/R <i>replaced</i>	2	37.70	✓ 75.40
FRONT BUMPER <i>replaced</i>	1	655.20	✓ 655.20
FRONT BUMPER INNER SPONGE <i>cracked</i>	1	326.50	✓ 326.50
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	625.90	✓ 625.90
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	25.00	✗ 50.00
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	21.00	✗ 21.00
FRONT GRILLE <i>cracked</i>	1	356.20	✓ 356.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	64.90	✓ 64.90
FRONT GRILLE LOWER MOULDING <i>new</i>	1	85.00	✗ 85.00
FRONT HEADLAMP L/R <i>cracked</i>	2	489.90	✓ 979.80
FRONT HEADLAMP LOWER GARNISH L/R <i>torn</i>	2	320.00	✓ 640.00
FRONT TOP PANEL <i>new</i>	1	251.40	✗ 251.40
REAR BUMPER <i>replaced</i>	1	485.90	✓ 485.90
REAR BUMPER LH REFLECTOR <i>new</i>	1	61.90	✗ 61.90
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	37.20	✗ 74.40
REAR BUMPER SPONGE <i>cracked</i>	1	94.00	✓ 94.00

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAKASAGO INTERNATIONAL (S) PTE LTD
 5 SUNVIEW ROAD
 SINGAPORE 627616

Contact : 67791077 97506590

TAX INVOICE

Repair Code : CLM17097

Date in : 14/02/2022

Vehicle Num. : GBG923B

Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Chassis/Eng# : VSKYBAM20Z0141642/K9KC400D056519

REAR BUMPER TOW HOOK COVER <i>new</i>	1	15.00	+ 15.00
REAR END PANEL (INNER) <i>Dented.</i>	1	697.00	- 697.00
REAR END PANEL TOP GARNISH <i>Rehd</i>	1	83.90	- 83.90
REAR LH TAILGATE <i>Disto h d</i>	1	1469.60	- 1,469.60
REAR LH TAILGATE 'LOGO' EMBLEM <i>3 new</i>	1	64.90	- 64.90
REAR LH TAILGATE 'NV200' EMBLEM	1	136.00	- 136.00
REAR LH TAILGATE DEAR LINK <i>new</i>	1	90.00	+ 90.00
REAR LH TAILGATE HINGES <i>new</i>	2	107.20	+ 214.40
REAR LH TAILGATE MECHANISM LOCK (LOWER) <i>Dented</i>	1	115.90	✓ 115.90
REAR LH TAILGATE MECHANISM LOCK (TOP) <i>new</i>	1	108.90	+ 108.90
REAR LH TAILGATE TRIM COVER <i>Rehd</i>	1	213.00	- 213.00
REAR LH TAILGATE WIPER MOTOR <i>Dented</i>	1	305.80	- 305.80
REAR LH TAILLAMP <i>crack d</i>	1	277.20	- 277.20
REAR RH TAILGATE <i>Dented</i>	1	1102.20	✓ 1,102.20
REAR RH TAILGATE MECHANISM LOCK (LOWER) <i>Rehd new</i>	1	115.90	+ 115.90
REAR RH TAILGATE TRIM COVER <i>new</i>	1	200.00	+ 200.00
REAR RH TAILGATE WEATHER (VERTICAL) <i>new</i>	1	72.60	+ 72.60
REAR TAILGATE CENTER LOCK MECHANISM <i>Dented</i>	1	253.80	✓ 253.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAKASAGO INTERNATIONAL (S) PTE LTD
 5 SUNVIEW ROAD
 SINGAPORE 627616

Contact : 67791077 97506590

TAX INVOICE

Repair Code : CLM17097
 Date in : 14/02/2022
 Vehicle Num. : GBG923B
 Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
 Chassis/Eng# : VSKYBAM20Z0141642/K9KC400D056519


REAR TAILGATE REVERSE CAMERA	<i>9348</i>	1	1125.00	1125.00
REAR TAILGATE WEATHER STRIP	<i>8413.00</i>	1	88.90	88.90
Subtotal before discount				11,923.50
Percentage discount 10%				1,192.35
Sub-total 1				10,731.15
ENGINE INTERCOOLER	<i>2121.60</i>	1	2121.60	2121.60
FLOOR TOP PANEL TRIM COVER	<i>400.00</i>	1	400.00	400.00
FRONT AIR GUIDE GARNISH CLIPS L/R - SET	<i>30.00</i>	2	30.00	60.00
FRONT BUMPER CLIPS - SET	<i>50.00</i>	1	50.00	50.00
FRONT GRILLE CLIPS - SET	<i>30.00</i>	1	30.00	30.00
FRONT NUMBER PLATE	<i>35.00</i>	1	35.00	35.00
FRONT NUMBER PLATE HOLDER	<i>50.00</i>	1	50.00	50.00
REAR BUMPER CLIPS - SET	<i>50.00</i>	1	50.00	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>250.00</i>	1	250.00	250.00
REAR END PANEL (OUTER)	<i>150.00</i>	1	150.00	150.00
REAR END PANEL TOP GARNISH CLIPS - SET	<i>40.00</i>	1	40.00	40.00
REAR LH TAILGATE '70KM' STICKER	<i>25.00</i>	1	25.00	25.00
REAR LH TAILGATE NUMBER PLATE	<i>35.00</i>	1	35.00	35.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAKASAGO INTERNATIONAL (S) PTE LTD
 5 SUNVIEW ROAD
 SINGAPORE 627616

Contact : 67791077 97506590



TAX INVOICE

Repair Code : CLM17097
 Date in : 14/02/2022
 Vehicle Num. : GBG923B
 Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/R
 Chassis/Eng# : VSKYBAM20Z0141642/K9KC400D056519

REAR LH TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR LH TAILGATE OUTER GARNISH CLIPS - SET	1	30.00	30.00
REAR LH TAILGATE WINDSCREEN SEAL	1	50.00	50.00
REAR LH TAILGATE WINDSCREEN SEALANT	1	60.00	60.00
REAR RH TAILGATE WINDSCREEN SEAL	1	50.00	50.00
REAR RH TAILGATE WINDSCREEN SEALANT	1	60.00	60.00
Subtotal before discount			3,596.60
Percentage discount 0%			0.00
Sub-total 2			3,596.60
Parts-total			14,327.75

LABOUR

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	30	80.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. <i>tailgate 8/600</i> <i>tailgate plan e/c</i>	80	280.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	120.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1200	1,800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1400	2,000.00
To apply anti-rust chemical on repaired and replaced panel.	80	100.00
To remove, reinstall tailgate mechanism and check for function	120	140.00
Labour Total		4,520.00
Parts & Labour Total		18,847.75

Adrian G
 1/9 15/02/22
 11 Days