

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6356 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJC 6537U

DATE	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1		TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2		TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	? X un
3		TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
4		TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100 ✓
5		TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES			: \$ 5,122.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJC 6537 U

S/N	PARTS DESCRIPTION	ESTIMATED QTY	CHARGES	DAMAGED PARTS & PRICES	REMARKS
1	FRONT BUMPER	1	\$	✓ 1,787.00 <i>de</i>	1429.60
2	FRONT BUMPER FIXING PARTS	1	\$	2,111.00 X	} un
3	FRONT BUMPER SECURING STRIP	2	\$	79.00 X	
4	FRONT BUMPER GRILLE - CENTER	1	\$	219.00 X	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$	254.00 X	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$	144.00 X	
7	RADIATOR GRILLE	1	\$	✓ 1,478.00 <i>Chg</i>	1182.40
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$	151.00 X <i>un</i>	} un
9	FRONT BUMPER FOAM FILLER PIECE	1	\$	✓ 139.00 <i>? cre</i>	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$	✓ 899.00 <i>? bt</i>	110.80
11	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	82.00 <i>? ?</i>	} un
12	FRONT BUMPER TOP COVER	1	\$	143.00 X	
13	"CAUTION" STICKER	1	\$	16.00 X	
14	AIR COND STICKER	1	\$	9.00 X	} un
15	FRONT BUMPER LOCK CARRIER BRACKET	1	\$	✓ 154.00 <i>? bt</i>	
16	FRONT BUMPER SUPPORT - LH / RH	2	\$	64.00 <i>? un</i>	} un
17	POP RIVET	4	\$	✓ 4.00 <i>? nei</i>	
18	HORN - LH	1	\$	134.00 X	
19	HORN SUPPORT - LH	1	\$	33.00 X	} un
20	FRONT PARKING AID SENSOR - INNER / OUTER	1	\$	244.00 X	
SUB TOTAL SPARE PARTS			:	\$ 8,144.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJC 6537 U

ESTIMATED		DAMAGED PARTS & PRICES		DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT.	REMARKS	
21	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	retun	
22	BONNET	1	\$ 3,425.00	bt 2740	
23	BONNET ATTACHMENT PARTS	1	\$ 431.00	X un	
24	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	rec 73.20	
25	BONNET STRIKER - LH	1	\$ 56.00	X	} n?
26	BONNET LOCK	1	\$ 228.00	X	
27	BONNET BOWDEN CABLE	1	\$ 64.00	X	
28	BONNET RELEASE LEVER	1	\$ 15.00	X	
29	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	X	
30	BONNET RELEASE CABLE COVER	1	\$ 11.00	X	
31	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	X	
32	FRONT WHEEL SPOILER	1	\$ 82.00	X	
33	HEADLIGHT - LH	1	\$ 7,693.00		
34	LIFT CYLINDER - LH	1	\$ 231.00	X	
	LIFT CYLINDER CORRUGATE PIPE	1	\$ 107.00	X	
	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	X dis 16.32	
	RADIATOR AIR GUIDE OUTER - LH	1	\$ 32.00	X	
	RADIATOR AIR GUIDE INNER - LH	1	\$ 14.00	X de 10.88	
	RADIATOR AIR GUIDE UPPER	1	\$ 19.00	X	
	FRONT NO PLATE	S/N	\$ 60.00	bt ✓	
	SUNDRIES		\$ 300.00	7 14.40	
TOTAL SPARE PARTS		:	\$ 21,360.00		
TOTAL LABOUR CHARGES		:	\$ 5,122.00		
GRAND TOTAL		:	\$ 26,482.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME: TANG

SURVEYED DATE:

AUTHORISED DATE:

EXCESS COST:

LIABILITY:

REMARKS:

Tang 9749544 / 62563561

Not Authorise 15/2/22 E.W.15

Exp: to be advise

Resurvey before paint

05 days tangline/khantb.on

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT