



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22001445/Etf3e2	
			Date: 30/05/2022	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLN 1424M
	Policy No.	Z21VP05028982	Coverage (\$)	0.00
	Claim No.	21/22/22/VP05/025420	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	15/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BM42A8G0347344	Colour	RED
	Odometer	14231 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	4 mm
	L/H Front Tyre	205/55 R16	MICHELIN	4 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	4 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/01/2022	Inspection Date	21/03/2022
	Survey held at	27A Tanjong Penjuru		
	Repairer	TRANS EUOKARS PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$56,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	