

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 32211

Date : 14-Feb-2022

PAGE : 1

Your Reference : Z21VP05028982
Accident Date : 29-Jan-2022

Our Ref : 021620 / MH

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

Not Authorized

Murray B & Pain

Ex ?? 7 days

ESTIMATED COST OF REPAIR FOR MAZDA 3 4-DOOR SEDAN 1.5L (2017) SLN1424M
=====

- Bpr*
- 1 pc RH rear fender *Sm X*
 - 1 pc rear windscreen glass *Sm X*
 - 1 pc rear windscreen glass moulding *Sm X*
 - 1 pc RH rear door *Sm X*
 - 1 pc RH rear door weatherstrip *Sm X*
 - 1 pc RH rear door outer handle *Sm X*
 - 1 pc RH rear door outer handle seal *Sm X*
 - 1 pc RH rear door outer handle side *Sm X*
 - cover
 - 1 pc RH rear door outer handle side *Sm X*
 - cover seal
 - 1 pc RH rear door outer handle base *Sm X*
 - 1 pc RH rear door lock *RX*
 - 1 pc RH rear door lock catch *RX*
 - 1 pc RH rear door windows regulator *?*
 - carrier
 - 1 pc RH rear door inner trimboard *?*
 - 1 pc RH front door *RX*
 - 1 pc RH front door weatherstrip *Sm X*
 - 1 pc RH front door outer handle *Red*
 - 1 pc RH frt door outer handle seal *Sm X*
 - 1 pc RH frt door outer handle side *Sm X*
 - cover
 - 1 pc RH frt door outer handle side *Sm X*
 - cover seal
 - 1 pc RH frt door outer handle base *Sm X*

Add 15% : 0.00

0.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VP05028982
Our Ref : 021620

Page : 2
No. : 32211

1 pc rear windscreen glass sealant
1 pc rear windscreen glass damping
seal

M 40.00 sn ☒
M 20.00 sn ☒

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

950.00 *900*

To remove and renew rear windscreen
glass and conduct water leak test.

120.00 ☒

To remove door's fittings

180.00 *60*

To putty and respray on affected
portions.

1,200.00 *800*

Total : S\$ 2,510.00
=====

Singapore Dollars Two Thousand Five Hundred and
Ten Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.