



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB22000619/Evf3e2-1	
			Date: 08/03/2022	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 2895T	Veh. Inspected	SLN 4090Y	
Policy No.	D21MFL0000447_01	Coverage (\$)	0.00	
Claim No.	MFL2022D0000295	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	15/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MR053REH104551906	Colour	SILVER	
Odometer	112096 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45Z R17	MICHELIN	5 mm	
L/H Front Tyre	215/45Z R17	MICHELIN	5 mm	
R/H Rear Tyre	215/45Z R17	MICHELIN	5 mm	
L/H Rear Tyre	215/45Z R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2022	Inspection Date	24/01/2022	
Survey held at	ENG HUP AUTOPARTS ACCESSORIES CO. 387J BLK 1 WOODLANDS ROAD SINGAPORE 677899			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	