



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001454/Uvf3e2	
			Date: 28/03/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 8720Y	Veh. Inspected	SLH 2938Y
	Policy No.	D-22098725MFVS/18	Coverage (\$)	0.00
	Claim No.	D22000434MFVS	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	15/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104559087	Colour	GREY
	Odometer	201962 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/02/2022	Inspection Date	15/02/2022
	Survey held at	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGA		
	Repairer	N-51 AUTOMOTIVE PL		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	