

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

Vehicle No: SLP 357U
Chasis No : W0L0MAP08G6117887
Engine No: B14XER19NG4135

GST Ref. No: 20-000027-Z

Invoice No: CGI-ASC-22IR01256G

Invoice Date: 1/7/2022

DESCRIPTION

**AMOUNT
SGD**

Parts

No.	Qty.	Description	Price (SGD)
1	1	REAR BUMPER UPPER	1,415.00
2	1	REAR FOG LAMP	234.00

Total: 1649.00
Less 10%: 164.90
Parts Total : 1484.10

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	650.00
2	Carry out spray painting on accident affected area. (Rear bumper)	550.00
3	Remove and refit reverse sensor (Labour)	40.00

Labour Total : 1240.00

Other

No.	Other Description	Price (SGD)
1	Rear Number Plate	35.00
2	Rear Bumper clip Set	25.00

Other Total : 60.00

Total : \$2,784.10
GST (7%) \$194.89
Grand Total: \$2,978.99

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.