

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST202-097

DATE : 21-Feb-2022

POLICY NO. : FWD PNCV2020-00000370-01

VEHICLE REG. NO. : SLZ5973E

VEHICLE MAKE : FIAT BRAVO 1.4L 150HP MANUAL

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Front Fender RH	1	\$ 600.00	\$ 600.00
2	Front Fender Shield RH	1	\$ 450.00	\$ 450.00
3	Front Fender Clips	10	\$ 12.00	\$ 120.00
4	Front Fender Signal Cover LH	1	\$ 85.00	\$ 85.00
5	Front Bonnet	1	\$ 950.00	\$ 950.00
6	Front Bonnet Insulator	1	\$ 320.00	\$ 320.00
7	Front Bonnet Insulator Clips	1	\$ 12.00	\$ 12.00
8	Front Bumper	1	\$ 800.00	\$ 800.00
9	Front Bumper Clips	10	\$ 12.00	\$ 120.00
10	Front Bumper Lower	1	\$ 320.00	\$ 320.00
11	Front Bumper Retainer LH	1	\$ 50.00	\$ 50.00
12	Front Absorber/Reinforcement	1	\$ 650.00	\$ 650.00
13	Front Headlamp LH	1	\$ 620.00	\$ 620.00
14	Front Support Panel	1	\$ 920.00	\$ 920.00
15	Front Fog Lamp LH	1	\$ 350.00	\$ 350.00
16	Front Fog Lamp Garnish LH	1	\$ 150.00	\$ 150.00
Total Spare Parts				\$ 6,517.00
<u>SPECIAL NETT</u>				
17	Tyre Rim (R17)	1	\$ 250.00	\$ 250.00
Total Special Nett				\$ 250.00
<u>LABOUR</u>				
18	Spray Painting Front Bumper, Front Fender LH, Front Bonnet Including Blending	1	\$ 700.00	\$ 700.00
19	Remove, Replace and Refit Accident Affected Areas	1	\$ 700.00	\$ 700.00
20	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,430.00
Amount Before Excess				\$ 8,197.00
Add GST @ 7%				573.79
Total Amount Payable				\$ 8,770.79

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.