

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

SP2000438618

Policy No: _____

10.02.2022

Date: _____

Accident Date : 08.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R			
1pc	Bonnet		380.00
1pc	Bonnet Center Rubber Seal		15.00
1pc	Bonnet Lock		65.00
1pc	Grille		180.00
1pc	Grille Emblem		15.00
1pc	Grille Top Chrome Garnish		160.00
1pc	Grille Bracket (Center)		45.00
2pcs	Grille Brackets (Side)		19.00
1pc	Front Bumper		180.00
12pcs	Front Bumper Clips	1.50	18.00
1pc	Front Bumper Reinforcement		180.00
2pcs	Front Bumper Top Retainers	42.00	84.00
1pc	Front Bumper Center Air Grille		65.00
1pc	Front Bumper Lower Lip		120.00
1pc	Front Bumper Fog Lamp		120.00
1pc	Front Bumper Fog Lamp Cover		20.00
2pcs	Front Bumper Corner Retainers	10.00	20.00
2pcs	Headlamps (LED)	850.00	1,700.00
1pc	Radiator		480.00
1pc	Air Con Condenser		400.00
1pc	Air Con Condenser Side Air Guide		28.00
1pc	Front Windscreen Glass		1,000.00
1pc	Front Windscreen Glass Moulding		100.00
			5,394.00
	Cost Plus 10%		539.40
			5,933.40
	Front Number Plate		45.00 SN
	Front Windscreen Glass Sealant		25.00 SN
	Front Windscreen Glass Fastener		12.00 SN
	Front Windscreen Glass IU Bracket		180.00 SN
	Front Windscreen Glass Solar Heat Film		70.00 SN
	Front Windscreen Glass Shade Film		
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Dismantle Replace Front Windscreen		100.00
		C/F	6,395.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SP2000438618

Accident Date : 08.02.2022

Date: 10.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R		
		B/F	6,395.40
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00
	Labour Charge - Panel Beating, Repairing Front Chassis Member, Inner Panel, Support Panel, Front N/S Fender And Part Replacement		700.00
	To Respray Affected Areas		800.00
		Total :	8,015.40