

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

SP2000438618

Policy No:

10.02.2022

Date:

Accident Date : 08.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R			
1pc	Bonnet / <i>bue</i>		380.00
1pc	Bonnet Center Rubber Seal / <i>twi</i>		15.00
1pc	Bonnet Lock / <i>bt</i>		65.00
1pc	Grille / <i>CPA</i>		180.00
1pc	Grille Emblem / <i>MC</i>		15.00
1pc	Grille Top Chrome Garnish / <i>CPA</i>		160.00
1pc	Grille Bracket (Center) ?		45.00
2pcs	Grille Brackets (Side) ?		19.00
1pc	Front Bumper / <i>DE</i>		180.00
12pcs	Front Bumper Clips / <i>MC</i> ?	1.50	18.00
1pc	Front Bumper Reinforcement		180.00
2pcs	Front Bumper Top Retainers ?	42.00	84.00
1pc	Front Bumper Center Air Grille ?		65.00
1pc	Front Bumper Lower Lip ?		120.00
1pc	Front Bumper Fog Lamp ?		120.00
1pc	Front Bumper Fog Lamp Cover ?		20.00
2pcs	Front Bumper Corner Retainers ?	10.00	20.00
2pcs	Headlamps (LED) ?	850.00	1,700.00
1pc	Radiator ?		480.00
1pc	Air Con Condenser ?		400.00
1pc	Air Con Condenser Side Air Guide ?		28.00
1pc	Front Windscreen Glass / <i>scr</i>		1,000.00
1pc	Front Windscreen Glass Moulding / <i>MC</i>		100.00
			5,394.00
	Cost Plus 10%		539.40
			5,933.40
	Front Number Plate / <i>bt</i>		45.00 SN
	Front Windscreen Glass Sealant / <i>MC</i>		25.00 SN
	Front Windscreen Glass Fastener / <i>MC</i>		12.00 SN
	Front Windscreen Glass IU Bracket ?		180.00 SN
	Front Windscreen Glass Solar Heat Film ?		70.00 SN
	Front Windscreen Glass Shade Film ?		
	To Conduct Electrical Check, Focus Headlamp		30.00 ✓
	To Dismantle Replace Front Windscreen		100.00 ✓

C/F

6,395.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SP2000438618

Accident Date : 08.02.2022

Date: 10.02.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No SNA7702R		
	To Remove / Refit Air Con Condenser & Refill Air Con Gas	B/F	6,395.40
	Labour Charge - Panel Beating, Repairing Front Chassis Member, Inner Panel, Support Panel, Front N/S Fender And Part Replacement		120.00
	To Respray Affected Areas		700.00
			800.00
		Total :	8,015.40

Guo Biang.
Partly Part
No. Authorise
5days

Excess TBA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: