



DETAILS

Source: MRM-SG
Version: 1.0 (Last Synchronised: 15 Feb 2022)
Model: M1-MPV
TOYOTA WISH 1.8 (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's
(Price-denominated Standard List)
Print Code: Accord Auto Services Pte Ltd/SGK8671U/15/02/2022 12:13
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

QTY	Part No.	Particulars	%Disc	%Depr	Amount	
1		*FRONT HEADLAMP LH	CM	0.00	*320.00 F	L
1		*FRONT HEADLAMP LOWER BRACKET	CM	0.00	*60.00 F	L
1		*FRONT BUMPER	Availent	0.00	*200.00 F	L
1		*FRONT BUMPER SIDE RETAINER LH & RH	N/S CM	0.00	*50.00 F	L
1		*FRONT BUMPER CENTRE GRILLE	Av	0.00	*55.00 F	L
1		*FRONT LH FOGLAMP GARNISH	Sn	0.00	*20.00 F	X
1		*FRONT LH FENDER	Bu	0.00	*195.00 F	L
1		*FRONT LH FENDER SHIELD	D/S	0.00	*75.00 F	L
1		*FRONT LH FENDER SIGNAL LIGHT	Sn	0.00	*20.00 F	X
1		*FRONT SHOCK ABSORBER LH & RH	Sn	0.00	*320.00 F	X
1		*FRONT ABSORBER MOUNTING LH & RH	Sn	0.00	*110.00 F	X
1		*FRONT ABSORBER DUST COVER LH & RH	Sn	0.00	*30.00 F	X
1		*FRONT ABSORBER STOPPER LH & RH	Sn	0.00	*24.00 F	X
1		*FRONT KNUCKLE ARM LH & RH	N/S Bu	0.00	*320.00 F	L
1		*FRONT WHEEL BEARING HUB LH & RH	N/S Sn	0.00	*170.00 F	L
1		*FRONT WHEEL BEARING LH & RH	N/S Sn	0.00	*90.00 F	L
1		*FRONT LOWER ARM LH & RH	Sn	0.00	*150.00 F	X
1		*FRONT BALL JOINT LH & RH	Sn	0.00	*80.00 F	X
1		*STEERING RACK END LH & RH	Sn	0.00	*150.00 F	X
1		*TIE ROD END LH & RH	Sn	0.00	*100.00 F	X
1		*STEERING RACK	X	0.00	*900.00 F	X
1		*REAR AXLE	Bu	0.00	*700.00 F	L
1		*REAR SHOCK ABSORBER LH & RH	N/S Bu	0.00	*170.00 F	L
1		*REAR ABSORBER MOUNTING LH & RH	N/S Bu	0.00	*140.00 F	L
1		*REAR ABSORBER DUST COVER LH & RH	Sn	0.00	*60.00 F	X
1		*REAR ABSORBER STOPPER LH & RH	Sn	0.00	*30.00 F	X
1		*REAR WHEEL BEARING HUB LH & RH	N/S Sn	0.00	*470.00 F	L
1		*REAR WHEEL BRAKE DRUM LH & RH	N/S Sn	0.00	*260.00 F	X
1		*REAR BRAKE PUMP LH & RH	N/S Sn	0.00	*120.00 F	X
1		*FRONT ABS SENSOR LH & RH	Sn	0.00	*310.00 F	X
1		*REAR BUMPER	Bu	0.00	*230.00 F	L
1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Bu	0.00	*60.00 F	L
1		*REAR BUMPER REFLECTOR LH & RH	Sn	0.00	*50.00 F	X
1		*REAR RH LAMP	CM	0.00	*195.00 F	L
1		*REAR LH LAMP	Sn	0.00	*195.00 F	X

se part.

Sub Total (\$\$)	6,429.00
+ Margin on L,N Items 10.00% (\$\$)	642.90
Total Parts (\$\$)	7,071.90

Accord Auto Services Pte Ltd/SGK8671U/15/02/2022 12:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Particulars	Amount
<u>Miscellaneous Items</u>		
1	FRONT & REAR REVERSE SENSOR	560.00
1	FRONT BUMPER CLIPS	35.00
3	FRONT FENDER SHIELD CLIPS	70.00
4	REAR BUMPER CLIPS	35.00
5	REAR FENDER SHIELD CLIPS	70.00
6	RIM 16	2,000.00
7	TYRE - 205/55/R16	390.00
Sub Total (S\$)		3,160.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00
4	TO REMOVE/REFIX REAR AXLE, TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	280.00
5	TO REMOVE/REFIX FRONT TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	280.00
6	TO REMOVE/REFIX FRONT TYRE, RIM & UNDERCARRIAGE REPLACEMENT	New	180.00
7	WHEEL ALIGNMENT	New	100.00
Gross Labour Cost (S\$)			3,160.00

Accord Auto Services Pte Ltd/SGK8671U/15/02/2022 12:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

11/2/22 @ 4250/1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: