

TP Car Pac
Ashes.

GBE338/R 2011 Dec.

Hyundai Starex. 2497 cc

KMFNBXTJLC4407955.

Front Number Plate.	cracked	30(SN)	✓
Front Number Plate Holder	cracked	30(SN)	✓
Front Bumper	Deformed	424.	✓
Front Bumper Clips.	new	30(SN)	✓
Front Bumper Side Holder	x2	35x2 = 70	✓
Front Bumper Lower Garnish.	new	394.	X
Front Bumper Lower Grille.	cracked	422	✓
Front Bumper Reinforcement.	new	323	X
Front Bumper Sponge	cracked	155	✓
Front Grille	cracked	398.	✓
Front Grille Clips.	new	20(SN)	✓
Front Grille Logo.	new	52.	✓
Headlamp x02	cracked	21x2 = 1242	✓

GBC 3381R.

Front Support Panel Top Cover	XHP neu	152	X
Front Support Panel Top Cover clips.	XHP neu	20(SN)	X
Air Can Fan	Cracked	462	/
Air Can Condenser	XHP neu	1082	X
Radiator	XHP neu	951	X.
Rear Number Plate	3 XHP neu	30(SN)	X
Rear Number Plate Holder		30(SN)	X
Rear Bumper Distorted		435	/
Rear Bumper Clips. Nec		30(SN)	/
Rear Bumper Side Holder x 02	XHP	38 x 2 = 76.	/
Rear Bumper Top Garnish.	Deformed	98	/
Rear Bumper Reinforcement.	Distorted	347	/
Rear Bumper Sponge.	Cracked	114	/

GBC 3381R.

Reverse Sensor	Damaged	280(SN) 200(SN)
Reer End Panel	Distorted	586 ✓
Reer End Panel Top Garnish.	Deformed	132 ✓
Reer End Panel Top Garnish Cips.	Nec	20(SN) ✓
Reer End Panel Sealant.	Nec	60(SN) ✓
Taillap x 02	Cracked	385 x 2 = 770 ✓
Taillap Lower Apron x 02.	LH torn	95 x 2 = 190 95.
Tailgate	Distorted	2318 ✓
Tailgate Lock	Damaged	214 ✓
Tailgate Weatherstrip	Cut	195 ✓
Tailgate Outer Garnish.	N4	242 X
Tailgate Inner Trim Board	Behind	253 ✓
Tailgate Inner Trim Board Cips.	N	30(SN) ✓
Tailgate Dampers x 02	N4	280 x 2 = 560 X
Tailgate Glass Moulding.	Nec	286 ✓
Tailgate Glass Sealant.		60(SN) ✓

GBC 3381R.

Hyundai Logo.	} Nec	55	✓
Hyundai Wording.		48	✓
H I Emblem.		58	✓
70km/h Stickers.		10(SN)	✓

Rees Exhaust Pipe.	} X4 Nec	1280	X
Rees Exhaust Pipe Mounting.		45	X
Rees Exhaust Pipe Gasket.		38	X

9305

7444

S.N: 520

GBC 3381 R.

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To spray tuff coat

To remove upholstery

To remove exhaust pipe

To remove tailgate glass

To transfer tailgate fittings.

To remove condenser and to top
up air con gas

To remove radiator and to
coolant

~~2000~~ 1400

~~2000~~ 1700

~~100~~ 60

~~100~~ 50

~~150~~ 60

~~150~~ 60

150 X

~~180~~ 120

~~150~~ 80

120 X

120 X

Total: 11494

1/s: 9.2K.

10 Days.

LKA Auto Consultants please notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9,200

10 days