

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 04 Apr 2022

## **Preliminary Advice**

Insured Vehicle No	: SLL740S	Accident Date	: 11/02/2022
TP Vehicle No	: SJL4349L	Assignment Date	: 15/02/2022
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 21
Date of Inspection	: 22/2/2022		
Inspection At	: BIFROST AUTO PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,674.29
Revised Amount	:S\$	21,169.97
Check Items (Estimated)	:S\$	0.00
Total	:S\$	21,169.97
Lump Sum Repair	:S\$	10,700.00

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	5,291.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,709.00

### **Remarks**

- ( X ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( X ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .