

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJL4349L

Make & Model: Mitsubishi Lancer

Chassis number: JMYSTCS3A8U009696

2008

No.	Description of spare parts	Qty	Amount
1	Bootlid	1	\$ 557.00 663.90
2	Bootlid "Lancer" emblem	1	\$ 28.00 ✓ 28.00
3	Bootlid centre emblem	1	\$ 48.00 ✓ 48.00
4	Bootlid "GLX" emblem	1	\$ 24.00 ✓ 24.00
5	Bootlid number plate garnish	1	\$ 195.70 265.70
6	Bootlid number plate garnish clips (set)	1	\$ 20.00 50.00
7	Bootlid RH hinge	1	\$ 50.00 76.10
8	Bootlid LH hinge	1	\$ 50.00 76.10
9	Bootlid lock	1	\$ 78.00 ✓ 78.00
10	Bootlid lock catch	1	\$ 21.00 ✓ 21.00
11	Bootlid lock cable	1	\$ 40.00 97.00
12	Bootlid weatherstrip	1	\$ 166.00 173.80
13	Rear bumper	1	\$ 689.00 ✓ 689.00
14	Rear bumper clips (set)	1	\$ 30.00 70.00
15	Rear bumper beam	1	\$ 122.00 175.00
16	Rear bumper RH side beam	1	\$ 46.00 ✓ 46.00
17	Rear bumper LH side beam	1	\$ 46.00 ✓ 46.00
18	Rear windscreen glass rubber moulding	1	\$ 34.00 ✓ 34.00
19	Rear LH fender	1	\$ 684.00 ✓ 684.00
20	Rear LH fender inner trim	1	\$ 203.50 232.00
21	Rear LH fender inner trim clips (set)	1	\$ 20.00 50.00
22	Rear LH fender splash shield	1	\$ 33.00 ✓ 33.00
23	Rear LH fender splash shield clips (set)	1	\$ 20.00 28.00
24	Rear RH fender	1	\$ 684.00 ✓ 684.00
25	Rear RH fender inner trim	1	\$ 203.50 232.00
26	Rear RH fender inner trim clips (set)	1	\$ 20.00 50.00
27	Rear RH fender splash shield	1	\$ 33.00 ✓ 33.00
28	Rear RH fender splash shield clips (set)	1	\$ 20.00 28.00
29	RH taillamp	1	\$ 489.20 513.00
30	RH taillamp sponge gasket	1	\$ 21.00 ✓ 21.00
31	RH taillamp lock clips (set)	1	\$ 12.00 23.00
32	RH taillamp panel	1	\$ 155.00 176.00

DDV ✓
 } NECV ✓
 BR ✓
 NEC ✓
 BT ✓
 JM ✓
 BT ✓
 MIS ✓
 TN ✓
 BR ✓
 NEC ✓
 BT ✓
 NEC ✓
 DD ✓
 TN ✓
 NEC ✓
 DD ✓
 TN ✓
 NEC ✓
 } NEC ✓
 BR ✓
 NEC ✓
 NEC ✓
 DD ✓

33	LH taillamp	1	\$ 489.20	513.00	BRV
34	LH taillamp sponge gasket	1	\$	✓ 21.00	NEC
35	LH taillamp lock clips (set)	1	\$ 12.00	23.00	
36	LH taillamp panel	1	\$ 155.00	176.00	DDV
37	End panel	1	\$ 407.00	582.00	DDV
38	End panel inner garnish	1	\$ 135.00	178.00	BRV
39	End panel inner garnish clips (set)	1	\$ 30.00	50.00	NEC
40	Spare tyre panel	1	\$ 587.00	808.40	DDV
41	Spare tyre panel inner insulator	1	\$ 150.00	178.00	NEC
42	Spare tyre top board cover	1	\$ 142.00	202.00	BRV
43	Spare tyre top board cover mat	1	\$	105.40	NNX
44	Exhaust silencer	1	\$ 478.00	755.30	DDV
45	Exhaust silencer gasket	1	\$	✓ 34.00	NEC
46	Exhaust silencer rubber hangers	2	\$	✓ 72.40	NEC
47	Exhaust centre pipe	1	\$ 724.00	883.50	BTV
48	Exhaust centre pipe gasket	1	\$	✓ 34.00	NEC
49	Rear RH chassis member	1	\$ 663.00	704.50	BTV
50	Bonnet	1	\$ 629.00	667.00	BTV
51	Bonnet RH hinge	1	\$	✓ 66.00	BTV
52	Bonnet LH hinge	1	\$	✓ 66.00	
53	Bonnet lock	1	\$	✓ 55.00	JMV
54	Bonnet lock cable	1	\$ 28.00	98.00	MIS
55	Bonnet inner rubber	1	\$	✓ 34.00	NEC
56	Front bumper	1	\$ 580.00	713.00	BRV
57	Front bumper clips (set)	1	\$ 30.00	60.00	NEC
58	Front bumper reinforcement	1	\$	✓ 155.00	BTV
59	Front bumper lower centre grille	1	\$	✓ 78.00	BRV
60	Front bumper number plate holder	1	\$	✓ 46.00	NEC
61	Front bumper RH side retainer	1	\$ 25.40	45.00	NEC
62	Front bumper LH side retainer	1	\$ 25.40	45.00	NEC
63	Front bumper RH fog lamp cover	1	\$	✓ 67.00	BRV
64	Front bumper LH fog lamp cover	1	\$	67.00	NNX
65	Front bumper lower cover	1	\$	✓ 145.00	BRV
66	Front bumper lower cover clips (set)	1	\$ 30.00	60.00	NEC
67	Front RH fender	1	\$	✓ 487.00	DDV
68	Front RH fender splash shield	1	\$	✓ 101.00	TN
69	Front RH fender splash shield clips (set)	1	\$ 30.00	60.00	NEC
70	Front LH fender	1	\$	487.00	NDX
71	Front LH fender splash shield	1	\$	101.00	TN
72	Front LH fender splash shield clips (set)	1	\$ 30.00	60.00	NEC
73	Front grille RH	1	\$	✓ 93.00	BRV
74	Front grille RH clips (set)	1	\$ 10.00	25.00	NEC
75	Front grille LH	1	\$	✓ 93.00	BRV
76	Front grille LH clips (set)	1	\$ 10.00	25.00	NEC
77	Front grille holder	1	\$	✓ 167.00	NEC
78	Front grille emblem	1	\$ 32.00	42.00	NEC
79	Headlamp LH	1	\$	✓ 488.00	BRV
80	Headlamp LH lock clips	1	\$	✓ 5.00	NEC
81	Headlamp RH	1	\$	✓ 488.00	BRV
82	Headlamp RH lock clips	1	\$	✓ 5.00	NEC

	realign all affected panels and areas			
2	Spray painting on affected areas and panels		\$ 1200.00 1800.00	✓
3	Check wiring and lighting system		\$ 30.00 80.00	✓
4	Apply rust coating chemical on affected areas and panels		\$ 180.00	NNX
5	Remove and reinstall rear windscreen glass to assist repair		\$ 120.00 200.00	✓
6	Remove and replace rear bumper reverse sensors to assist repair		\$ 60.00 70.00	✓
7	Remove and replace rear inner trim, garnish, boards, roof lining, seats and carpet to assist repair		\$ 250.00 450.00	✓
8	Remove and reinstall fuel tank, pipes and sensors to assist repair		\$ 120.00	NNX
9	Remove and replace exhaust silencer, centre pipe and gaskets to assist repair		\$ 80.00 220.00	✓
10	Mount vehicle on chassis alignment bench to repair both chassis frame and members		\$ 250.00 550.00	✓
11	Remove and reinstall rear undercarriage parts to assist repair		\$ 450.00	NNX
12	Test drive and adjust wheel alignment system		\$ 100.00	NNX
	(FRONT PORTION)			
13	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		\$ 800.00 1200.00	✓
14	Spray painting on affected areas and panels		\$ 1000.00 1300.00	
15	Check wiring and lighting system		\$ 30.00 60.00	✓
16	Apply rust coating chemical on affected areas and panels		\$ 80.00	NNX
17	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas		\$ 120.00 200.00	✓
18	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant		\$ 100.00 200.00	✓
19	Refocus and adjust headlamps assy		\$ 50.00	NNX

Total \$ 10,320.00

Spare Parts: \$ 19,249.29

Special Nett: \$ 1,105.00

Labour: \$ 10,320.00

Total Amount: \$ 30,674.29

Survey 24/2/2022
 1530hrs
 Resurvey 28/2/2022
 1600hrs

PanTs 15,194.97

SN 535.00

Labour 5,440.00

21,169.97

@20% 4,233.99

16,935.98

Lump sum repair
 Repair days 21

LS 16,950/2

NV 10,709/2

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: