



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2203450

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 06/06/2022
Reference CC4/LPC22001470/Apa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 8495T
Insured Veh. SLH 5552G
Claim No. 21/22/22/VP05/025457
Policy No. Z21VP05027870
Accident Date 13/02/2022
Inspection Date 15/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22001470/Apa3q2 Date: 06/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 5552G	Veh. Inspected	SMT 8495T	
Policy No.	Z21VP05027870	Coverage (\$)	0.00	
Claim No.	21/22/22/VP05/025457	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	15/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOURAN	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WVGZZZ1TZW044210	Colour	BLUE	
Odometer	82137 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	PIRELLI	6 mm	
L/H Front Tyre	215/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	215/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	215/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/02/2022	Inspection Date	15/02/2022	
Survey held at	POLYMATH GARAGE PTE LTD 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE S(417868)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 8495T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,258.00	1,258.00
2	REAR BUMPER SIDE HOLDER @\$58.00	NOT NECESSARY	116.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	604.00	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED	198.00	198.00
1	FRONT BUMPER SIDE GRILLE LH	CUT	69.00	69.00
1	FRONT BUMPER SIDE LAMP LH	CRACKED	287.00	287.00
1	FRONT BUMPER SPONGE	CRACKED	95.00	95.00
1	FRONT BUMPER UNDERCOVER	TORN	189.00	189.00
1	FRONT BUMPER LOWER BEAM	NOT NECESSARY	249.00	-
1	FRONT BUMPER LOWER SIDE CHROME	CUT	48.00	48.00
1	HEADLAMP LH	CUT	1,738.00	1,738.00
1	FRONT GRILLE	CRACKED	685.00	685.00
1	FRONT GRILLE INNER BRACKET	CRACKED	184.00	184.00
1	FRONT GRILLE LOGO	NECESSARY	82.00	82.00
	LESS 10% DISCOUNT		-580.20	-483.30
			5,221.80	4,349.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER UNDERCOVER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
			80.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	300.00
	SPRAY PAINTING.		500.00	250.00
	WIRING.		50.00	30.00
			1,050.00	580.00
	GRAND TOTAL		6,351.80	5,009.70

Report Ref No. CC4/LPC22001470/Apa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CC4/LPC22001470/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8495T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8495T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8495T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

